

VMware Deliverable Release Notes

This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

[HPE Integrity Superdome X](#)
[HPE Superdome Flex](#)

Information on HPE Synergy supported VMware ESXi OS releases, HPE ESXi Custom Images and HPE Synergy Custom SPPs is available at:

[OS Support Tool for HPE Synergy](#)

Information on HPE Synergy Software Releases is available at:

[HPE Synergy Software Releases - Overview](#)

Gen10 SPP 2025.07.00.00 Release Notes for VMware ESXi 8.0

[BIOS - System ROM](#)
[Driver - Lights-Out Management](#)
[Driver - Network](#)
[Driver - Storage Controller](#)
[Firmware - Network](#)
[Firmware - Storage Controller](#)
[Firmware - Storage Fibre Channel](#)
[Software - Management](#)
[Software - Storage Controller](#)
[Software - Storage Fibre Channel](#)
[Software - System Management](#)

BIOS - System ROM

[Top](#)

ROM Flash Firmware Package - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers

Version: 3.50_04-17-2025 (**Recommended**)

Filename: U39_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant XL170/XL190 Gen10 System ROM - U38

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers
Version: 3.50_04-17-2025 (**Recommended**)
Filename: U40_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 System ROM - U40

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers
Version: 3.50_04-17-2025 (**Recommended**)
Filename: U31_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL160 Gen10/DL180 Gen10 System ROM - U31

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 (U43) Servers

Version: 3.60_05-16-2025 (**Recommended**)

Filename: U43_3.60_05_16_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Mehlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.05.005.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE System ROM - U43

Release Version:

3.60_05-16-2025

Last Recommended or Critical Revision:

3.60_05-16-2025

Previous Revision:

3.52_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Removed Expired SUSE and Vmware Certificates.

Problems Fixed:

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Mehlw IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.05.005.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

Removed Expired SUSE and Vmware Certificates.

ROM Flash Firmware Package - HPE Proliant DL20 Gen10 Plus Servers

Version: 2.40_05-16-2025 (**Recommended**)

Filename: U60_2.40_05_16_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE System ROM - U60

Release Version:

2.40_05-16-2025

Last Recommended or Critical Revision:

2.40_05-16-2025

Previous Revision:

2.34_03-11-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

ROM Flash Firmware Package - HPE ProLiant DL325 Gen10 (A41) Servers

Version: 3.50_03-21-2025 (**Recommended**)

Filename: A41_3.50_03_21_2025.fwpkg

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL325 Gen10 System ROM - A41

Release Version:

3.50_03-21-2025

Last Recommended or Critical Revision:

3.50_03-21-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Problems Fixed:

None

Known Issues:

None

Enhancements

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Enhancements/New Features:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL360 Gen10 (U32) Servers
Version: 3.50_04-17-2025 (**Recommended**)
Filename: U32_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL360 Gen10 System ROM - U32

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant DL380 Gen10 (U30) Servers
Version: 3.50_04-17-2025 (**Recommended**)
Filename: U30_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE DL380 Gen10 System ROM - U30

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant DL385 Gen10 (A40) Servers

Version: 3.50_03-21-2025 (**Recommended**)

Filename: A40_3.50_03_21_2025.fwpkg

Important Note!**Important Notes:**

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL385 Gen10 System ROM - A40

Release Version:

3.50_03-21-2025

Last Recommended or Critical Revision:

3.50_03-21-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Problems Fixed:

None

Known Issues:

None

Enhancements

Important Notes:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors. This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Enhancements/New Features:

This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

This revision of the System ROM includes AMD reference code NaplesPI 1.0.0.Q for AMD 1st Generation EPYC processors.

Known Issues:

None

ROM Flash Firmware Package - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers

Version: 3.50_04-17-2025 (**Recommended**)

Filename: U34_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL560 Gen10/DL580 Gen10 System ROM - U34

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant MicroServer Gen10 Plus v2 (U64) Servers

Version: 2.40_05-16-2025 (**Recommended**)

Filename: U64_2.40_05_16_2025.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant MicroServer Gen10 Plus v2 System ROM - U64

Release Version:

2.40_05-16-2025

Last Recommended or Critical Revision:

2.40_05-16-2025

Previous Revision:

2.34_03-11-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

ROM Flash Firmware Package - HPE ProLiant ML110 Gen10 (U33) Servers
Version: 3.50_04-17-2025 (**Recommended**)
Filename: U33_3.50_04_17_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant ML110 Gen10 System ROM - U33

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 (U44) Servers
Version: 3.60_05-16-2025 (**Recommended**)
Filename: U44_3.60_05_16_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Mehlw IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.05.005.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant ML30 Gen10 System ROM - U44

Release Version:

3.60_05-16-2025

Last Recommended or Critical Revision:

3.60_05-16-2025

Previous Revision:

3.52_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Removed Expired SUSE and VMware Certificates.

Problems Fixed:

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes

Important Notes:

This version of the System ROM contains updates aligned with the Intel Mehlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 05.01.05.005.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

Removed Expired SUSE and VMware Certificates.

ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 Plus Servers

Version: 2.40_05-16-2025 (**Recommended**)

Filename: U61_2.40_05_16_2025.fwpkg

Important Note!

Important Notes:

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant ML30 Gen10 Plus System ROM - U61

Release Version:

2.40_05-16-2025

Last Recommended or Critical Revision:

2.40_05-16-2025

Previous Revision:

2.34_03-11-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel Tatlow IPU 2025.2 update. This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 06.00.03.700 (2.30_01_07_2025).

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system may encounter RSOD and fail to update firmware while performing firmware update.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

ROM Flash Firmware Package - HPE ProLiant ML350 Gen10 (U41) Servers

Version: 3.50_04-17-2025 (**Recommended**)

Filename: U41_3.50_04_17_2025.fwpkg

Important Note!**Important Notes:**

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant ML350 Gen10 System ROM - U41

Release Version:

3.50_04-17-2025

Last Recommended or Critical Revision:

3.50_04-17-2025

Previous Revision:

3.42_02-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Removed Expired SUSE and VMware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Fixes**Important Notes:**

This version of the System ROM contains updates aligned with the Intel IPU 2025.2 updates.

This version of the System ROM should be paired with Server Platform Services (SPS) Firmware 04.01.05.105.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the system might have false IML message "Processor X, DIMM Y - This NVDIMM is NOT a HPE SmartMemory NVDIMM".

Addressed an issue where the system might trigger BitLocker Recovery after reboot.

Known Issues:

None

Enhancements

Removed Expired SUSE and Vmware Certificates.

Improved detection and interaction with certain PCIe cards during UEFI HBA discovery process.

ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus (A43) Servers

Version: 3.72_05-16-2025 (**Optional**)

Filename: A43_3.72_05_16_2025.fwpkg

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.G for AMD 3rd Generation EPYC processors. This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE ProLiant DL325/DL325 v2/DL345 Gen10 Plus System ROM - A43

Release Version:

3.72_05-16-2025

Last Recommended or Critical Revision:

3.72_05-16-2025

Previous Revision:

3.70_03-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Problems Fixed:

Addressed an issue where system may hang at POST when there are 8TB system memory installed with certain configuration.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.G for AMD 3rd Generation EPYC processors. This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where system may hang at POST when there are 8TB system memory installed with certain configuration.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

ROM Flash Universal Firmware Package - HPE ProLiant DL360/DL380 Gen10 Plus (U46) Servers
Version: 2.42_06-13-2025 (**Recommended**)
Filename: U46_2.42_06_13_2025.fwpkg

Important Note!

Important Notes:

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE System ROM - U46

Release Version:

2.42_06-13-2025

Last Recommended or Critical Revision:

2.42_06-13-2025

Previous Revision:

2.40_04-18-2025

Firmware Dependencies:

None

Enhancements/New Features:

Added Uncore Frequency RAPL to system RBSU (System Configuration > BIOS/Platform Configuration (RBSU) > Power and Performance Options >Uncore Freq RAPL).

Problems Fixed:

Addressed an issue where the Maximum/Minimum Uncore Frequency values might still be configurable when Uncore Frequency Scaling is set to AUTO from OneView.

Known Issues:

None

Fixes

Important Notes:

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where the Maximum/Minimum Uncore Frequency values might still be configurable when Uncore Frequency Scaling is set to AUTO from OneView.

Known Issues:

None

Enhancements

Added Uncore Frequency RAPL to system RBSU (System Configuration > BIOS/Platform Configuration (RBSU) > Power and Performance Options >Uncore Freq RAPL).

ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385/DL385 v2 Gen10 Plus (A42) Servers
Version: 3.72_05-16-2025 (**Optional**)
Filename: A42_3.72_05_16_2025.fwpkg

Important Note!

Important Notes:

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.G for AMD 3rd Generation EPYC processors. This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Deliverable Name:

HPE DL365 Gen10 Plus/DL385 Gen10 Plus/DL385 v2 Gen10 Plus System ROM - A42

Release Version:

3.72_05-16-2025

Last Recommended or Critical Revision:

3.72_05-16-2025

Previous Revision:

3.70_03-21-2025

Firmware Dependencies:

None

Enhancements/New Features:

Updated multi-language translation.

Problems Fixed:

Addressed an issue where system may hang at POST when there are 8TB system memory installed with certain configuration.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Fixes**Important Notes:**

This revision of the System ROM includes AMD reference code MilanPI 1.0.0.G for AMD 3rd Generation EPYC processors. This revision of the System ROM includes AMD reference code RomePI 1.0.0.M for AMD 2nd Generation EPYC processors.

Details about reported security vulnerabilities and their mitigation can be found at the following link [Security Bulletin Library | HPE Support](#).

Firmware Dependencies:

None

Problems Fixed:

Addressed an issue where system may hang at POST when there are 8TB system memory installed with certain configuration.

Addressed an issue where the Name field of the Logical Drive under MR controller page might be missing or changed unintentionally after exiting and going back to the MR controller page.

Known Issues:

None

Enhancements

Updated multi-language translation.

Driver - Lights-Out Management[Top](#)

HPE iLO Native Driver for ESXi 8.0 and ESXi 9.0

Version: 10.9.0 (**Recommended**)

Filename: ilo-driver_800.10.9.0.17-1OEM.800.1.0.20613240_24608328.zip

Fixes

The product addressed a probabilistic PSOD when repeatedly doing the OS reboot.

Enhancements

- o Add support for the new ESXi 9.0
- o Remove support for the ESXi 7.0.

Driver - Network[Top](#)

HPE Broadcom NetXtreme-E Drivers for VMware vSphere 8.0

Version: 2025.05.00 (**Recommended**)

Filename: cp066625.compsig; cp066625.zip

Important Note!

- o This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.
- o HPE recommends the *HPE Broadcom NetXtreme-E Firmware Version, 233.1.135007* or later, for use with this driver.

Fixes

- o This product fixes the issue where ESXi Datastore not seen when NPAR is enabled.
- o This product fixes the issue where PSOD is seen when enable NPAR using 2 NICs.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- o HPE Ethernet 10Gb 2-port 535T Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- o HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

- o HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE
- o Broadcom BCM57608 Ethernet 100Gb 2-port QSFP112 Adapter for HPE
- o Broadcom BCM57608 Ethernet 100Gb 2-port QSFP112 OCP3 Adapter for HPE

HPE Intel i40en Driver for VMware vSphere 8.0

Version: 2024.11.00 **(Recommended)**

Filename: cp063149.compsig; cp063149.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.25.0 or later, for use with this driver.

Fixes

- o This product addressed the multicast traffic handling on PF0.
- o This product addressed the per-queue statistics for native mode.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- o HPE Ethernet 1Gb 2-port 368i Adapter
- o HPE Ethernet 1Gb 4-port 369i Adapter
- o HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 563i Adapter
- o HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- o HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- o HPE Ethernet 10Gb 2-port 568i Adapter
- o HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

HPE Intel igbn Driver for VMware vSphere 8.0

Version: 2025.05.00 **(Recommended)**

Filename: cp066052.compsig; cp066052.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.26.1 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with firmware.

Supported Devices and Features

These drivers support the following network adapters:

- o HPE Ethernet 1Gb 2-port 361T Adapter
- o HPE Ethernet 1Gb 2-port 361i Adapter
- o HPE Ethernet 1Gb 2-port 363i Adapter
- o HPE Ethernet 1Gb 4-port 366FLR Adapter
- o HPE Ethernet 1Gb 4-port 366T Adapter
- o HPE Ethernet 1Gb 4-port 366i Adapter
- o HPE Ethernet 1Gb 4-port 366i Communication Board
- o Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter for HPE
- o Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter for HPE
- o Intel(R) I350 Gigabit Network Connection

HPE Intel ixgben Driver for VMware vSphere 8.0

Version: 2024.03.00 **(Recommended)**

Filename: cp058394.compsig; cp058394.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.23.0 or later, for use with this driver.

Enhancements

This product enhanced the compatibility with firmware of Fortville 9.4.

Supported Devices and Features

These drivers support the following network adapters:

- o HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 561T Adapter
- o HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- o HPE Ethernet 10Gb 2-port 562T Adapter
- o HPE Ethernet 10Gb 2-port 562FLR-T Adapter

HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 8.0

Version: 2025.03.00 (**Recommended**)

Filename: cp064342.compsig; cp064342.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxx.xml file.

HPE recommends the firmware provided as below for use with these drivers,

- o HPE QLogic FastLinQ Firmware Package for Arrowhead adapters, version 8.65.23 or later.
- o HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware, version 4.20.0 or later.

Fixes

This product fixes a PSOD issue which is caused by the memory leak.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 521T Adapter
- o HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- o HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- o HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- o HPE StoreFabric CN1200R-T Converged Network Adapter
- o HPE StoreFabric CN1300R Converged Network Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCU OCP3 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- o HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HQCU OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 8.0

Version: 2025.03.00 (**Recommended**)

Filename: cp064345.compsig; cp064345.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.37.0 or later, for use with this driver.

Fixes

- o This product corrects an issue which fix TSO (TCP Segmentation Offload) issue when single segment is larger than pkt length.
- o This product corrects an issue which PSOD while freeing DMA during 'esxcli qlfastlinq qcc' command execution.

Supported Devices and Features

These drivers support the following network adapters:

- o HPE Ethernet 10Gb 2-port 530T Adapter
- o HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- o HPE FlexFabric 10Gb 2-port 533FLR-T Adapter
- o HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- o HPE FlexFabric 10Gb 4-port 536FLR-T Adapter

Intel icen Driver for VMware vSphere 8.0

Version: 2025.05.00 (**Recommended**)

Filename: cp064886.compsig; cp064886.zip

Important Note!

- o This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CP0xxxx.xml file.
- o HPE recommends the firmware provided in *Intel Firmware Package For E810 Ethernet Adapter*, version 4.71 or later, for use with these drivers.

Fixes

This product fixes to align DDP with the new FW version and NVM 4.7.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- o Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE
- o Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- o Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE
- o Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
- o Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE
- o Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

net-mst kernel module driver component for VMware ESXi 8.0 Update 3

Version: 2025.03.17 **(Recommended)**

Filename: cp052054.compsig; cp052054.zip

Important Note!

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the HPE vib depot.hpe.com webpage, plus an HPE specific CPXXXX.xml file.

Prerequisites

NA

Enhancements

NMST version 4.31.0.150

This version is supported on VMware ESXi 8.0 Update 3 only.

Supported Devices and Features

HPE Part Number	Device Name	PSID
764282-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
P24837-B21	HPE Ethernet 10/25Gb 2-port 642SFP28 Adapter	HPE0000000054
P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HP_1200111023
764285-B21	HPE InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HPE InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
825110-B21	HPE InfiniBand EDR/Ethernet 100Gb 1-port 840QSFP28 Adapter	HP_2180110032
825111-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 840QSFP28 Adapter	HP_2190110032
872726-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 841QSFP28 Adapter	HPE0000000009
879482-B21	HPE InfiniBand FDR/Ethernet 40/50Gb 2-port 547FLR-QSFP Adapter	HPE0000000022
868779-B21	HPE Synergy 6410C 25/50Gb Ethernet Adapter	HPE0000000006
779793-B21	HPE Ethernet 10Gb 2-port 546SFP+ Adapter	HP_1200111023
779799-B21	HPE Ethernet 10Gb 2-port 546FLR-SFP+ Adapter	HP_2240110004
817749-B21	HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter	HP_2690110034
817753-B21	HPE Ethernet 25Gb 2-port 640SFP28 Adapter	HP_2420110034
P21927-B21	HPE Ethernet 100Gb 2-port QSFP28 MCX516A-CCHT Adapter	MT_0000000417
P10112-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX562A-ACAI OCP3 Adapter	MT_0000000241
P13188-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter	MT_0000000416
P11341-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4621A-ACAB OCP3 Adapter	MT_0000000238
P21930-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCHT Adapter	MT_0000000414
874253-B21	HPE Ethernet 100Gb 1-port 842QSFP28 Adapter	HPE0000000014
P25960-B21	HPE Ethernet 100Gb 2-Port QSFP56 MCX623106AS-CDAT Adapter	MT_0000000437
P06154-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port 940QSFP56 x16 Adapter	HPE0000000034
P06250-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port 940QSFP56 x16 Adapter	HPE0000000035
P06251-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port 940QSFP56 x16 Adapter	HPE0000000036
P23664-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port MCX653105A-HDAT QSFP56 x16 Adapter	MT_0000000451
P23665-B21	HPE InfiniBand HDR100/Ethernet 100Gb 1-port MCX653105A-ECAT QSFP56 x16 Adapter	MT_0000000452
P23666-B21	HPE InfiniBand HDR100/Ethernet 100Gb 2-port MCX653106A-ECAT QSFP56 x16 Adapter	MT_0000000453
P10180-B21	Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	MT_0000000435
P31246-B21	HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter	MT_0000000591
P31323-B21	HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter	MT_0000000592
P31348-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter	MT_0000000593
P31324-B21	HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter	MT_0000000594
P42041-B21	Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000551

Driver - Storage Controller[Top](#)

HPE MR416i-p, MR216i-p, MR416i-a, MR216i-a Gen10 plus Controllers and MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p, MR408i-p Gen11 Controllers Driver (64-bit) for vSphere 8.0

Version: 2025.05.01 (**Recommended**)

Filename: cp064821.compsig; cp064821.zip

Important Note!

This new 7.32 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of July 2025.

- o Actual Version is 7.732.03.00

Fixes

- o Fix a00145710en_us: HPE MR Gen11 and Gen10 Plus Storage Controllers - Purple Screen of Death (PSOD) May Be Observed When Updating Controller Firmware Via Service Pack for ProLiant (SPP) in Remote Deployment Mode With a VMware ESXi OS.
- o Fix a potential issue that driver may access destroyed reset mutex lock in the watch dog timer and causes the ASSERT.

Enhancements

- o Modified the Driver to display driver type (Inbox/OOB) while displaying the driver version in kernel logs.
- o Debug ability improvements which store the reason in string format for allocating DMA address. It will be easy to check the reason for allocating particular DMA address while analyzing system crash issues.
- o Remove SAS2.5/lower device IDs from driver file.

HPE ProLiant Gen10 Smart Array and Gen10 Plus and Gen11 Smart RAID Controller Driver for VMware vSphere 8.0 (Driver Component).

Version: 2025.02.01 (**Recommended**)

Filename: cp062918.compsig; cp062918.zip

Important Note!

- o This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com, plus an HPE specific CPXXXX.xml file.
- o Actual ESXi8.0 driver version is 80.4704.0.108

Enhancements

- o Improve the tolerance of error handling.
- o Enhancement of DMA engine attributes to prevent PSOD.

Firmware - Network[Top](#)

Broadcom Firmware Package for BCM5741x adapters

Version: 233.1.135.7 (**Recommended**)

Filename: bcm233.1.135.7.pup.fwpkg; bcm233.1.135.7.pup.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 233.0.148.0 or later
- o HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.3-233.0.152. or later
- o HPE Broadcom NetXtreme-E Drivers for VMware, version 2025.05.00 or later

Fixes

- o This product fixes an issue where the AssignablePhysicalNetworkPorts hyperlink under NetworkDeviceFunctions was not expanded correctly with Redfish expand queries.
- o This product fixes an issue where VLAN-tagged packets were looped back or misrouted due to VEB behavior, causing TCP retransmissions and link instability in LACP configurations.
- o This product fixes an issue where the adapter did not correctly report all supported link speeds (1G/10G/25G) via ethtool.
- o This product fixes an issue where Broadcom NXE NICs could overheat and become unrecognized when MCTP was disabled.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter

Broadcom Firmware Package for BCM5750x adapters

Version: 233.1.135.7 (**Recommended**)

Filename: bcm233.1.135.7_Thor.pup.fwpkg; bcm233.1.135.7_Thor.pup.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.
 For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Broadcom NetXtreme-E Driver for Microsoft Windows Server, version 233.0.148.0 or later
- o HPE Broadcom NetXtreme-E Drivers for Linux, version 1.10.3-233.0.152.2 or later
- o HPE Broadcom NetXtreme-E Drivers for VMware, version 2025.05.00 or later

Fixes

- o This product fixes an issue where the AssignablePhysicalNetworkPorts hyperlink under NetworkDeviceFunctions was not expanded correctly with Redfish expand queries.
- o This product fixes an issue where VLAN-tagged packets were looped back or misrouted due to VEB behavior, causing TCP retransmissions and link instability in LACP configurations.
- o This product fixes an issue where the adapter did not correctly report all supported link speeds (1G/10G/25G) via ethtool.

Supported Devices and Features

This product supports the following network adapters:

- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Broadcom NX1 Online Firmware Upgrade Utility for VMware
 Version: 1.42.0 (**Recommended**)
 Filename: CP066652.compsig; CP066652.zip

Important Note!

This software package contains combo image v20.33.41 with the following firmware versions:

NIC	Boot Code Version	PXE Version	NCSI Version	UEFI Version
BCM 5719 1GbE 4p BASE-T Adptr	1.60	21.6.4	1.5.61	21.6.90
BCM 5719 1GbE 4p BASE-T OCP3 Adptr	1.60	21.6.4	1.5.61	21.6.90
BCM 5719 1GbE 4p BASE-T LOM Adptr	1.60	21.6.4	1.5.61	21.6.90
BCM 5720 1GbE 2p BASE-T LOM Adptr	1.43	21.6.4	1.5.61	21.6.90

Prerequisites

This product requires the appropriate driver for your device and operating system to be installed before the firmware is updated.

Fixes

This product fixes an issue where MBA configuration reset to defaults on port 3 and 4 for BCM5719 4-port adapters after updating firmware.

Supported Devices and Features

This product supports the following network adapters:

- o Broadcom BCM5720 Ethernet 1Gb 2-port BASE-T LOM Adapter for HPE
- o Broadcom BCM5719 Ethernet 1Gb 4-port Base-T Adapter for HPE
- o Broadcom BCM5719 Ethernet 1Gb 4-port Base-T OCP3 Adapter for HPE
- o Broadcom BCM5719 Ethernet 1Gb 4-port Base-T LOM Adapter for HPE

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware
 Version: 226.1.107000 (B) (**Recommended**)
 Filename: CP065662.compsig; CP065662.zip

Important Note!

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2023.09.00 or later, for use with this firmware.

This software package contains NVM Image version 226.1.107000 with the following firmware versions:

NIC	Bootcode Version	NCSI Version	MBA Version	UEFI Version	RoCE Version
HPE Ethernet 10Gb 2-port 535FLR-T Adapter	226.0.145.0	226.0.145.0	226.0.135.0	226.0.135.0	226.0.145.0
HPE Ethernet 10Gb 2-port 535T Adapter					
HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter					
HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter					

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- o This product addressed the NC-SI passthrough algorithm for some FRU-reading commands from platform side.
- o This product addressed the packet forwarding rule while receiving packet which is bigger than 9600 jumbo size.
- o This product addressed the link failure under FreeBSD OS after changing link speed.
- o This product addressed the failure of bringing up VFs of SRIOV when doing on and off switch.
- o This product addressed adapter not responsive when work under heavy loading with 128 VMs.
- o The product addressed status reporting of PLDM sensor monitoring with BMC.
- o This product addressed the link-flap after link down or warm boot.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- o HPE Ethernet 10Gb 2-port 535T Adapter
- o HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter
- o HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware

Version: 226.1.107.0 (B) (**Recommended**)

Filename: CP065663.compsig; CP065663.zip

Important Note!

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2023.09.00 or later, for use with this firmware.

This software package contains NVM Image version 226.1.107000 with the following firmware versions:

NIC	Bootcode Version	NCSI Version	MBA Version	UEFI Version	RoCE Version
HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter	226.0.145.0	226.0.145.0	226.0.135.0	226.0.135.0	226.0.145.0
HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter					
HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter					
HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter					
HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter					
HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter					
HPE Ethernet 10/25Gb 4-port SFP28 BCM57504 Adapter					
HPE Ethernet 10/25Gb 4-port SFP28 BCM57504 OCP3 Adapter					

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- o This product addressed device lost symptom after continuously ungraceful restart on BCM57414 OCP3 adapter.
- o This product addressed some RDE pattern format for some LLDP properties.
- o This product addressed the NC-SI passthrough with BMC when device is under idle mode.
- o This product addressed new mechanism for loading factory default.

Enhancements

- o This product enhanced the device self-diagnostic matrix and MAC verification.
- o This product enhanced the link-speed calculation for internal variable.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 Adapter
- o HPE Ethernet 10Gb 2-port BaseT BCM57416 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ BCM57412 OCP3 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 BCM57414 Adapter
- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE
- o Broadcom BCM57504 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware

Version: 5.26.0 (**Recommended**)

Filename: CP066633.compsig; CP066633.zip

Important Note!

HPE recommends *HPE Broadcom NetXtreme-E Drivers for VMware*, versions 2025.05.00 or later, for use with this firmware.

This software package contains NVM Image version 233.1.135007 with the following firmware versions:

NIC	Bootcode Version	NCSI Version	MBA Version	UEFI Version	RoCE Version
HPE Ethernet 10Gb 2-port 535FLR-T Adapter	233.0.151.0	233.0.151.0	233.0.146.0	233.0.146.0	233.0.151.0
HPE Ethernet 10Gb 2-port 535T Adapter					
HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter					
HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ Adapter					
HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter					

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- o This product fixes an issue where VLAN-tagged packets were looped back or misrouted due to VEB behavior, causing TCP retransmissions and link instability in LACP configurations.
- o This product fixes an issue where the adapter did not correctly report all supported link speeds (1G/10G/25G) via ethtool.
- o This product fixes an issue where Broadcom NXE NICs could overheat and become unrecognized when MCTP was disabled.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 537SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 537SFP+ FLR Adapter
- o HPE Ethernet 10Gb 2-port 535T Adapter
- o HPE Ethernet 10Gb 2-port 535FLR-T Adapter
- o HPE Ethernet 10/25Gb 2-port 631SFP28 Adapter
- o HPE Ethernet 10/25Gb 2-port 631FLR-SFP28 Adapter

HPE Broadcom NX1 Online Firmware Upgrade Utility VMware for HPE ProLiant Gen10 server series Only.

Version: 1.42.0 (**Recommended**)

Filename: CP066649.compsig; CP066649.zip

Important Note!

- o **This component ONLY support HPE ProLiant Gen10 server series.**

This software package contains combo image v20.33.41 with the following firmware versions:

NIC	Boot Code Version	PXE Version	NCSI Version	UEFI Version
HPE Ethernet 1Gb 2-port 330i Adapter (22BD)	2.10	21.6.4	1.5.61	21.6.90
HPE Ethernet 1Gb 4-port 331i Adapter (22BE) HPE Ethernet 1Gb 4-port 331FLR Adapter HPE Ethernet 1Gb 4-port 331T Adapter	1.60	21.6.4	1.5.61	21.6.90
HPE Ethernet 1Gb 2-port 332i Adapter (22E8) HPE Ethernet 1Gb 2-port 332T Adapter	1.43	21.6.4	1.5.61	21.6.90

For previous firmware versions prior to v20.19.51, please refer to the link : <https://www.hpe.com/global/swpublishing/MTX-4f19da2bceff4b73a31531d71e>

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

This product fixes an issue where MBA configuration reset to defaults on port 3 and 4 for BCM5719 4-port adapters after updating firmware.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 1Gb 2-port 330i Adapter (22BD)
- o HPE Ethernet 1Gb 4-port 331i Adapter (22BE)
- o HPE Ethernet 1Gb 4-port 331FLR Adapter
- o HPE Ethernet 1Gb 4-port 331T Adapter
- o HPE Ethernet 1Gb 2-port 332i Adapter (22E8)
- o HPE Ethernet 1Gb 2-port 332T Adapter

HPE Intel Online Firmware Upgrade Utility VMware for HPE ProLiant Gen9 and Gen10 server series Only.

Version: 3.26.1 (**Recommended**)

Filename: CP065264.compsig; CP065264.zip

Important Note!

- o This software package contains the following firmware versions for the below listed supported network adapters:

NIC	EEPROM/NVM Version	OROM Version	Single NVM Version
HPE Ethernet 1Gb 2-port 361i Adapter	8000119A	1.3772.0	N/A
HPE Ethernet 1Gb 2-port 361T Adapter	80001147	1.3772.0	N/A
HPE Ethernet 1Gb 4-port 366FLR Adapter	800011A1	1.3772.0	N/A
HPE Ethernet 1Gb 4-port 366T Adapter	800011F1	1.3772.0	N/A
HPE Ethernet 1Gb 2-port 368i Adapter	80003AC5	1.3772.0	N/A
HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter	80003AC2	1.3772.0	N/A
HPE Ethernet 1Gb 4-port 369i Adapter	80003AC3	1.3772.0	N/A
HPE Ethernet 10Gb 2-port 568i Adapter	80003AC4	1.3772.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter	80003AC2	1.3772.0	N/A
HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter	80003AC2	1.3772.0	N/A
HPE Ethernet 10Gb 2-port 563i Adapter	800035C0	1.1375.0	N/A
HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter	8000F231	1.3772.0	11.1.7
HPE Ethernet 10Gb 2-port 562FLR-T Adapter	800016F1	1.3772.0	10.55.3
HPE Ethernet 10Gb 2-port 562SFP+ Adapter	8000F232	1.3772.0	11.1.7
HPE Ethernet 10Gb 2-port 562T Adapter	800016EF	1.3772.0	10.55.3

The combo image v1.3772.0 includes: Boot Agent: 1GbE - v1.5.90, 10GbE - v2.4.54, 40GbE - v1.1.45 & UEFI Drivers: 1GbE - v9.8.79, 10GbE - v8.2.76, 40GbE - v5.0.17

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

This software package no longer contains Firmware for the below listed supported network adapters:

- HPE Ethernet 1Gb 2-port 363i Adapter
- HPE Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HPE Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 560SFP+ Adapter
- HPE Ethernet 10Gb 2-port 561FLR-T Adapter
- HPE Ethernet 10Gb 2-port 561T Adapter

- o The latest firmware version of above adapters, please refer to the link : https://support.hpe.com/connect/s/softwaredetails?language=en_US&softwareId=MTX_d7826493bb5a4aa69b4aa9a1d5&tab=releaseNotes

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with the latest drivers.

Supported Devices and Features

This package supports the following network adapters:

- o HPE Ethernet 1Gb 2-port 361i Adapter
- o HPE Ethernet 1Gb 2-port 361T Adapter
- o HPE Ethernet 1Gb 2-port 368FLR-MMT Adapter
- o HPE Ethernet 1Gb 2-port 368i Adapter
- o HPE Ethernet 1Gb 4-port 366FLR Adapter
- o HPE Ethernet 1Gb 4-port 366T Adapter
- o HPE Ethernet 1Gb 4-port 369i Adapter
- o HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 562FLR-T Adapter
- o HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- o HPE Ethernet 10Gb 2-port 562T Adapter
- o HPE Ethernet 10Gb 2-port 568FLR-MMSFP+ Adapter
- o HPE Ethernet 10Gb 2-port 568FLR-MMT Adapter
- o HPE Ethernet 10Gb 2-port 568i Adapter
- o HPE Ethernet 10Gb 2-port 563i Adapter

HPE QLogic FastLinQ Firmware Package for Arrowhead adapters
Version: 8.65.23 **(Recommended)**
Filename: ql_hp_ah_mbi_8.65.23_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.74.6.0-x or later
- o HPE QLogic FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.21.0 or later

- o HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2025.03.00 or later

This software package contains combo image v8.65.23. This combo image includes: Boot Code (MFW): 8.65.7.0, PXE: 2.0.19, and UEFI: 4.1.13.2.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10Gb 2-port 521T Adapter
- o HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- o HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- o HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Adapter
- o HPE StoreFabric CN1200R-T Converged Network Adapter
- o HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware
Version: 4.20.0 (**Recommended**)
Filename: CP064261.compsig; CP064261.zip

Important Note!

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2025.03.00 or later, for use with this firmware.

This software package contains combo image version v8.65.23 includes:

- o Boot Code (MFW): 8.65.7.0
- o UEFI: 4.1.13.2
- o PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware
Version: 8.55.12 (B) (**Recommended**)
Filename: CP065660.compsig; CP065660.zip

Important Note!

HPE recommends *HPE QLogic FastLinQ 10/25/50GbE Multifunction Drivers for VMware*, versions 2021.04.05 or later, for use with this firmware.

This software package contains combo image version v8.55.12 includes:

- Boot Code (MFW): 8.55.21.0
- UEFI: 4.1.11.2
- PXE: 2.0.19

The users will only see the combo image versions in the interactive mode firmware update or while using HPSUM/SPP to update the firmware on the supported adapters.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

This product addresses a pause flood condition on switch when attempting iPXE boot.

Enhancements

This product contains support PLDM firmware upgrade base improvements.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 521T Adapter
- HPE Ethernet 10Gb 2-port 524SFP+ Adapter
- HPE Ethernet 10/25Gb 2-port 621SFP28 Adapter
- HPE Ethernet 10/25Gb 2-port 622FLR-SFP28 Converged Network Adapter
- HPE StoreFabric CN1200R-T Converged Network Adapter
- HPE StoreFabric CN1300R Converged Network Adapter

HPE QLogic NX2 Online Firmware Upgrade Utility for VMware
 Version: 1.37.0 (**Recommended**)
 Filename: CP064334.compsig; CP064334.zip

Important Note!

HPE recommends HPE QLogic NX2 10/20GbE Multifunction Drivers for VMware, versions 2025.03.00 or later, for use with this firmware.

This software package contains combo image v7.19.27 with the following firmware versions:

NIC	Boot Code Version	PXE Version	UEFI Version	iSCSI Version	FCoE Version	CCM Version	L2 Version
HPE Ethernet 10Gb 2-port 530SFP+ Adapter HPE Ethernet 10Gb 2-port 530T Adapter	7.16.15	7.14.13	8.9.3	n/a	n/a	7.14.4	7.12.25
HPE Ethernet 10Gb 2-port 533FLR-T Adapter HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter HPE FlexFabric 10Gb 4-port 536FLR-T Adapter	7.16.15	7.14.13	8.9.3	7.14.0	7.14.3	7.14.4	7.12.25

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 530SFP+ Adapter
- HPE Ethernet 10Gb 2-port 530T Adapter
- HPE Ethernet 10Gb 2-port 533FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter

Intel Firmware Package For E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter
 Version: 4.71 (**Recommended**)
 Filename: HPE_E810_2CQDA2_O_SEC_4p71_PLDMoMCTP_80020037.fwpkg; HPE_E810_2CQDA2_O_SEC_4p71_PLDMoMCTP_80020037.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.
 For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- Intel ice Drivers for Linux, version 1.15.4-1 or later
- Intel icn Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- This product fixes an issue where the speed may be downgraded to Gen3.
- This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- Intel E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter
 Version: 4.71 (**Recommended**)
 Filename: HPE_E810_CQDA2_4p71_PLDMoMCTP_8002003C.fwpkg; HPE_E810_CQDA2_4p71_PLDMoMCTP_8002003C.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter for HPE

Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter

Version: 4.71 (**Recommended**)

Filename: HPE_E810_CQDA2_OCP_4p71_NCSIwPLDMoMCTP_80020036.fwpkg; HPE_E810_CQDA2_OCP_4p71_NCSIwPLDMoMCTP_80020036.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter

Version: 4.71 (**Recommended**)

Filename: HPE_E810_XXVDA2_SD_4p71_PLDMoMCTP_80020038.fwpkg; HPE_E810_XXVDA2_SD_4p71_PLDMoMCTP_80020038.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.
For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter

Version: 4.71 (**Recommended**)

Filename: HPE_E810_XXVDA2_SD_OCP_4p71_NCSIwPLDMoMCTP_8002003D.fwpkg; HPE_E810_XXVDA2_SD_OCP_4p71_NCSIwPLDMoMCTP_8002003D.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter

Version: 4.71 (**Recommended**)

Filename: HPE_E810_XXVDA4_FH_4p71_PLDMoMCTP_8002003E.fwpkg; HPE_E810_XXVDA4_FH_4p71_PLDMoMCTP_8002003E.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter for HPE

Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter

Version: 4.71 (**Recommended**)

Filename: HPE_E810_XXV4_OCP_4p71_NCSIwPLDMoMCTP_80020035.fwpkg; HPE_E810_XXV4_OCP_4p71_NCSIwPLDMoMCTP_80020035.json

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Intel ica Driver for Microsoft Windows Server, version 1.15.121.0 or later
- o Intel ice Drivers for Linux, version 1.15.4-1 or later
- o Intel icen Driver for VMware, version 2025.05.00 or later

This FW version does not support Port.Reset RDE metrics. This product will be enhance to improve the functions in the future release

Fixes

- o This product fixes an issue where the speed may be downgraded to Gen3.
- o This product fixes an issue where the Linux driver fails to load due to an EEPROM checksum error when the RDE:MACAddress property is patched.
- o This product fixes an issue where the NIC is not detected after performing the RDE patch operation on NetworkDeviceFunctions settings.
- o This product fixes an issue where the RDE: Setting property (AutoSpeedNegotiationEnabled) does not cause the property value to update, returning a code 400.
- o This product fixes an issue where the RDE fails to perform the get operation when the adapter is configured as pass-through.
- o This product fixes an issue where the RDE property (FlowControlStatus) does not report the correct status after the RDE property FlowControlConfiguration is set to Tx.
- o This product fixes an issue where the RDE patch operation fails on the AutoSpeedNegotiationEnabled property.

Supported Devices and Features

This product supports the following network adapters:

- o Intel E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter for HPE

Intel Online Firmware Upgrade Utility for VMware
Version: 3.26.1 (**Recommended**)
Filename: CP065266.compsig; CP065266.zip

Important Note!

This software package contains the following firmware versions for the below listed supported network adapters:

NIC	EEPROM/NVM Version	OROM Version	Single NVM Version	FW Version
HPE Ethernet 10Gb 2-port SFP+ OCP3 X710-DA2 Adapter	8000F8E2	1.3755.0	N/A	9.53
HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter	8000F8EE	1.3755.0	N/A	9.53
Intel I350-T4 Ethernet 1Gb 4-port BASE-T Adapter	8000123F	1.3755.0	N/A	N/A
Intel I350-T4 Ethernet 1Gb 4-port BASE-T OCP3 Adapter	80001234	1.3755.0	N/A	N/A
Intel(R) I350 Gigabit Network Connection (2-port)	8000119C	1.3755.0	N/A	N/A
Intel(R) I350 Gigabit Network Connection (4-port)	8000119D	1.3755.0	N/A	N/A

The combo image v1.3755.0 includes: Boot Agent: 1GbE - v1.5.90, 10GbE - v2.4.54, 40GbE - v1.1.45 & UEFI Drivers: 1GbE - v9.8.79, 10GbE - v8.2.76, 40GbE - v5.0.17

Single NVM Version is new firmware format which represent an unified version in place of the previously used EEPROM/NVM Version or OROM version.

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Enhancements

This product enhanced the compatibility with the latest drivers.

Supported Devices and Features

This package supports the following network adapters:

- o Intel(R) I350 Gigabit Network Connection (2-port)
- o Intel(R) I350 Gigabit Network Connection (4-port)
- o HPE Ethernet 1Gb 4-port BaseT I350-T4 Adapter
- o HPE Ethernet 1Gb 4-port BaseT I350-T4 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ X710-DA2 OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ X710-DA2 Adapter

Marvell FastLinQ Firmware Package for Arrowhead adapters
Version: 8.65.21 (**Recommended**)
Filename: ql_ah_mbi_open_8.65.21_pldm.fwpkg

Important Note!

For Firmware installation, there is no OS and drivers dependency.

For Firmware compatibility during production, HPE recommends the drivers for use with the firmware Package product as below,

- o Marvell FastLinQ 10/25/50 GbE Drivers for Microsoft Windows Server x64 Editions, version 8.72.21.0 or later
- o HPE QLogic FastLinQ 10/25/50 GbE Drivers for Linux, version 8.74.6.0-5 or later
- o HPE QLogic FastLinQ 10/25/50 GbE Multifunction Drivers for VMware, version 2025.03.00 or later

Enhancements

This product enhanced the compatibility with drivers.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCU OCP3 Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HQCU OCP3 Adapter
- o HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter

Marvell FastLinQ Online Firmware Upgrade Utility for VMware

Version: 8.55.12 (B) **(Recommended)**

Filename: CP065661.compsig; CP065661.zip

Important Note!

This software package contains combo image v8.55.12. This combo image includes:

- o PXE: 2.0.19
- o Boot Code (MFW): 8.55.22.0
- o UEFI: 6.1.8.2

Prerequisites

This product requires the appropriate driver for your device and operating system be installed before firmware is updated.

Fixes

- o This product contains support PLDM firmware upgrade base improvements.
- o This product addresses an overheat issue on the network adapters as below,

HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter

Enhancements

This product now supported NPAR enabling option.

Supported Devices and Features

This product supports the following network adapters:

- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HQCU OCP3 Adapter
- o HPE Ethernet 10/25Gb 2-port SFP28 QL41232HLCU Adapter
- o HPE Ethernet 10Gb 4-port SFP+ QL41134HLCU Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HLRJ Adapter
- o HPE Ethernet 10Gb 2-port BaseT QL41132HQRJ OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HQCU OCP3 Adapter
- o HPE Ethernet 10Gb 2-port SFP+ QL41132HLCU Adapter

Mellanox Firmware Package (FWPKG) - Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE

Version: 26.44.1036 **(Recommended)**

Filename: 26_44_1036-MCX631102AS-ADA_Ax.pldm.fwpkg; 26_44_1036-MCX631102AS-ADA_Ax.pldm.json

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6lxfirmwarev26441036/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 26.44.1036:

- o A reference counter issue that resulted in the firmware assertion 0x889f with CQ reference counter underflow to solve a race condition.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 26.44.1036:

- o Enabled the get_pf_mac_address function for all available PFs.
- o Enhanced traffic management of PTP packets to reduce their impact on regular network traffic.
- o Added a new NV config (SM_DISABLE, default 0) which, when enabled, blocks SMP traffic that does not originate from the SM.

- o Added the ability to set cable length as a parameter in the PFCC access register. The cable length is used in the calculation of RX lossless buffer parameters, including size, Xoff, and Xon thresholds.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P42044-B21	Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	MT_0000000575

Mellanox Firmware Package (FWPKG) - Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
Version: 26.44.1036 (**Recommended**)
Filename: 26_44_1036-MCX631432AS-ADA_Ax.pldm.fwpkg; 26_44_1036-MCX631432AS-ADA_Ax.pldm.json

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6lxfirmwarev26441036/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 26.44.1036:

- o A reference counter issue that resulted in the firmware assertion 0x889f with CQ reference counter underflow to solve a race condition.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 26.44.1036:

- o Enabled the get_pf_mac_address function for all available PFs.
- o Enhanced traffic management of PTP packets to reduce their impact on regular network traffic.
- o Added a new NV config (SM_DISABLE, default 0) which, when enabled, blocks SMP traffic that does not originate from the SM.
- o Added the ability to set cable length as a parameter in the PFCC access register. The cable length is used in the calculation of RX lossless buffer parameters, including size, Xoff, and Xon thresholds.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P42041-B21	Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000551

Mellanox Firmware Package (FWPKG) for Mellanox MCX562A-ACAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE
Version: 16.35.4030 (**Recommended**)
Filename: 16_35_4030-MCX562A-ACA_Ax_Bx.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16354030/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 16.35.4030:

- o VF FLR would get stuck when its PF triggered the FLR as well.
- o Unexpected source UDP port appeared in RoCE packets when the firmware ignored a non-PF driver configuration for RoCE source UDP port control (as set in SET_HCA_CAP.sw_r_roce_src_udp_port).

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.4030:

- o Added support for postponing QP timeout "retry exceeded" errors for traffic directed at specific destinations. This new capability prevents broken connections for destinations in downtime because of live migration.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P10112-B21	Mellanox MCX562A-ACAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	MT_0000000241

Mellanox Firmware Package (FWPKG) for Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE
Version: 22.44.1036 **(Recommended)**
Filename: 22_44_1036-MCX623105AS-VDA_Ax.pldm.fwpkg; 22_44_1036-MCX623105AS-VDA_Ax.pldm.json

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6dxfirmwarev22441036/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.44.1036:

- o Traffic would halt and recovery would be prevented when the emulation doorbell malfunctioned.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 22.44.1036:

- o Unified PTP is now supported across different VFs on the same PF.
- o Added a new NV config (SM_DISABLE, default 0) which, when enabled, blocks SMP traffic that does not originate from the SM.
- o Added the ability to set cable length as a parameter in the PFCC access register. The cable length is used in the calculation of RX lossless buffer parameters, including size, Xoff, and Xon thresholds.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P10180-B21	Mellanox MCX623106AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	MT_0000000435

Mellanox Firmware Package (FWPKG) for Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE
Version: 22.44.1036 **(Recommended)**
Filename: 22_44_1036-MCX623106AS-CDA_Ax.pldm.fwpkg; 22_44_1036-MCX623106AS-CDA_Ax.pldm.json

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6dxfirmwarev22441036/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 22.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 22.44.1036:

- o Traffic would halt and recovery would be prevented when the emulation doorbell malfunctioned.

Enhancements

Security Hardening Enhancements: This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device's firmware to this release to improve the firmware security and reliability of your device.

New features and changes included in version 22.44.1036:

- o Unified PTP is now supported across different VFs on the same PF.
- o Added a new NV config (SM_DISABLE, default 0) which, when enabled, blocks SMP traffic that does not originate from the SM.
- o Added the ability to set cable length as a parameter in the PFCC access register. The cable length is used in the calculation of RX lossless buffer parameters, including size, Xoff, and Xon thresholds.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P25960-B21	Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE	MT_0000000437

Mellanox Firmware Package(FWPKG) for HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter

Version: 16.35.4030 (**Recommended**)

Filename: 16_35_4030-MCX512F-ACH_Ax_Bx.pldm.fwpkg

Important Note!

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <https://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <https://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <https://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16354030its/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 16.35.4030:

- o VF FLR would get stuck when its PF triggered the FLR as well.
- o Unexpected source UDP port appeared in RoCE packets when the firmware ignored a non-PF driver configuration for RoCE source UDP port control (as set in SET_HCA_CAP.sw_r_roce_src_udp_port).

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.4030:

- o Added support for postponing QP timeout "retry exceeded" errors for traffic directed at specific destinations. This new capability prevents broken connections for destinations in downtime because of live migration.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P13188-B21	HPE Ethernet 10/25Gb 2-port SFP28 MCX512F-ACHT Adapter	MT_0000000416

NVIDIA Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter : HPE part numbers P31246-B21 and P31246-H21

Version: 16.35.4506 (**Recommended**)

Filename: 16_35_4506-MCX515A-CCA_HPE_Ax.pldm.fwpkg; 16_35_4506-MCX515A-CCA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx5firmwarev16354506/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 16.35.4506:

- o Incorrect MPLS packets discards flow occurred when the GLOBAL pause capability was disabled.

Enhancements

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

New features and changes included in version 16.35.4506:

- o Added address validation in MLNX OEM CMD 0x0032 (get debug info) to be 4- bytes aligned.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA Ethernet Only Adapters	Firmware Version	PSID
HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter(P31246-B21 and P31246-H21)	16.35.4506	MT_0000000591

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter : HPE part numbers P23664-B21 and P23664-H21

Version: 20.43.2566 (**Recommended**)

Filename: 20_43_2566-MCX653105A-HDA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653105A-HDA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- o Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter (P23664-B21 and P23664-H21)	20.43.2566	MT_0000000451

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter : HPE part numbers P31323-B21 and P31323-H21

Version: 20.43.2566 (**Recommended**)

Filename: 20_43_2566-MCX653435A-HDA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653435A-HDA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566lts/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- o Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A-HDAI Adapter (P31323-B21 and P31323-H21)	20.43.2566	MT_0000000592

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter : HPE part numbers P31324-B21 and P31324-H21

Version: 20.43.2566 (**Recommended**)

Filename: 20_43_2566-MCX653106A-HDA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653106A-HDA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	200GbE/50GbE	100GbE/25GbE	40GbE/10GbE	1GbE

HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566ts/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter(P31324-B21 and P31324-H21)	20.43.2566	MT_0000000594

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter : HPE part numbers P31348-B21 and P31348-H21

Version: 20.43.2566 (**Recommended**)

Filename: 20_43_2566-MCX653436A-HDA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653436A-HDA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

- HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
- Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
200GbE/50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	200GbE/50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566ts/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A-HDAI Adapter (P31348-B21 and P31348-H21)	20.43.2566	MT_0000000593

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter : HPE part numbers P23665-B21 and P23665-H21

Version: 20.43.2566 **(Recommended)**

Filename: 20_43_2566-MCX653105A-ECA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653105A-ECA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

- HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
- Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566ts/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter (P23665-B21 and P23665-H21)	20.43.2566	MT_0000000452

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter : HPE part numbers P23666-B21 and P23666-H21

Version: 20.43.2566 (**Recommended**)

Filename: 20_43_2566-MCX653106A-ECA_HPE_Ax.pldm.fwpkg; 20_43_2566-MCX653106A-ECA_HPE_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

ConnectX-6 VPI supports having one port as InfiniBand and the other port as Ethernet according to the following matrix of combinations.

Port #2 - InfiniBand				
Port #1 - Ethernet	HDR/HDR100	EDR	FDR	QDR
50GbE	supported	not supported	not supported	supported
100GbE/25GbE	supported	not supported	not supported	supported
40GbE/10GbE	supported	not supported	not supported	supported
1GbE	supported	not supported	not supported	supported

Port #2 - Ethernet				
Port #1 - InfiniBand	50GbE	100GbE/25GbE	40GbE/10GbE	1GbE
HDR / HDR100	supported	supported	not supported	supported
EDR	supported	supported	not supported	supported
FDR	not supported	not supported	not supported	not supported
QDR/SDR	supported	supported	not supported	supported

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx6firmwarev20432566/known+issues>

Prerequisites

FWPKG will work only if the firmware version flashed on the adapter is 20.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

Fixes

The following issues have been fixed in version 20.43.2566:

- o Resolved an issue that caused the SLRG register to be unreadable when using the SMP AccessRegister MAD.

Enhancements

No changes or new features have been included in version 20.43.2566.

Supported Devices and Features

This software package contains the following firmware versions:

NVIDIA VPI Adapter	Firmware Version	PSID
HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106A-ECAT Adapter (P23666-B21 and P23666-H21)	20.43.2566	MT_0000000453

NVIDIA Firmware Package (FWPKG) for HPE InfiniBand NDR200/Ethernet 200Gb 1-port OSFP PCIe5 x16 MCX75310AAS-HEAT Adapter : HPE part numbers P45642-B22 and P45642-H22

Version: 28.45.1200 (**Recommended**)

Filename: 28_45_1200-MCX75310AAS-HEAT_HPE2_Ax.pldm.fwpkg; 28_45_1200-MCX75310AAS-HEAT_HPE2_Ax.pldm.json

Important Note!

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

Disclaimer: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <http://www.nvidia.com/>, you are then leaving HPE.com. Please follow the instructions on <http://www.nvidia.com/> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <http://www.nvidia.com/>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available at: <https://docs.nvidia.com/networking/display/connectx7firmwarev28451200/known+issues>

Prerequisites

FWPKG will work only if the iLO5 firmware version is 2.30 or higher.

Fixes

The following fixes have been included in version 28.45.1200:

- o Fixed DC InfiniBand functionality.

Enhancements

New features and changes included in version 28.45.1200:

- o Introduced a 1ms delay for SPDM responses.

Supported Devices and Features

HPE Part Number	NVIDIA VPI Adapter	PSID
P45642-B22	HPE InfiniBand NDR200/Ethernet 200Gb 1-port OSFP PCIe5 x16 MCX75310AAS-HEAT Adapter (P45642-B22 and P45642-H22)	MT_0000001119

Online Firmware Upgrade Utility (ESXi 8.0) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter

Version: 1.0.1 (**Recommended**)

Filename: CP063146.compsig; CP063146.zip

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx firmware version 14.32.1010. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

No fixes have been included in firmware version 14.32.1900.

Enhancements

Firmware for the following device has been updated to 14.32.1900:

- o P11338-B21 (HPE Ethernet 10Gb 2-port 548SFP+ Adapter)

Security Hardening Enhancements

This release contains important reliability improvements and security hardening enhancements. NVIDIA recommends upgrading your devices firmware to this release to improve the devices' firmware security and reliability.

No new features or changes have been included in firmware version 14.32.1900.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P11338-B21	HPE Ethernet 10Gb 2-port 548SFP+ Adapter	HPE0000000038

Online Firmware Upgrade Utility (ESXi 8.0) for HPE Mellanox Ethernet only adapters

Version: 1.0.5 (**Recommended**)

Filename: CP063098.compsig; CP063098.zip

Important Note!

The Firmware Upgrade Utility has been split into 2 packages for Mellanox Ethernet Only NIC adapters, one supporting Synergy platforms and the other supporting ProLiant and Apollo platforms. This package supports Mellanox Ethernet Only NIC adapters on ProLiant and Apollo servers.

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx/ConnectX5 firmware version 14.32.1010/16.32.1010 (or later) respectively. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

No fixes have been included in firmware version 14.32.1900.

The following issues have been fixed in firmware version 16.35.4030:

- o VF FLR would get stuck when its PF triggered the FLR as well.
- o Unexpected source UDP port appeared in RoCE packets when the firmware ignored a non-PF driver configuration for RoCE source UDP port control (as set in SET_HCA_CAP.sw_r_roce_src_udp_port).

Enhancements

Firmware for the following devices has been updated to 14.32.1900:

- o 817749-B21 (HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter)
- o 817753-B21 (HPE Ethernet 25Gb 2-port 640SFP28 Adapter)

Firmware for the following device has been updated to 16.35.4030:

- o 874253-B21 (HPE Ethernet 100Gb 1-port 842QSFP28 Adapter)

Security Hardening Enhancements

This release contains important reliability improvements and security hardening enhancements. NVIDIA recommends upgrading your devices firmware to this release to improve the devices' firmware security and reliability.

No new features or changes have been included in firmware version 14.32.1900.

New features and changes included in firmware version 16.35.4030:

- o Added support for postponing QP timeout "retry exceeded" errors for traffic directed at specific destinations. This new capability prevents broken connections for destinations in downtime because of live migration.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
817749-B21	HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter	HP_2690110034
817753-B21	HPE Ethernet 25Gb 2-port 640SFP28 Adapter	HP_2420110034
874253-B21	HPE Ethernet 100Gb 1-port 842QSFP28 Adapter	HPE0000000014

Online Firmware Upgrade Utility (ESXi 8.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5 devices on VMware ESXi 8.0
Version: 1.0.5 (**Recommended**)
Filename: CP066778.compsig; CP066778.zip

Fixes

No new fixes have been added in version 12.28.2302.

The following issues have been fixed in version 16.35.4506:

- o Incorrect MPLS packets discards flow occurred when the GLOBAL pause capability was disabled.

Enhancements

Firmware for the following devices has been updated to 12.28.2302:

- o 825110-B21 (HPE InfiniBand EDR/Ethernet 100Gb 1-port 840QSFP28 Adapter)
- o 825111-B21 (HPE InfiniBand EDR/Ethernet 100Gb 2-port 840QSFP28 Adapter)

Firmware for the following devices has been updated to 16.35.4506:

- o 879482-B21 (HPE InfiniBand FDR/Ethernet 40/50Gb 2-port 547FLR-QSFP Adapter)
- o 872726-B21 (HPE InfiniBand EDR/Ethernet 100Gb 2-port 841QSFP28 Adapter)

Important : Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

No new Features and changes included in version 12.28.2302.

New features and changes included in version 16.35.4506:

- o Added address validation in MLNX OEM CMD 0x0032 (get debug info) to be 4- bytes aligned.

Supported Devices and Features

HPE Part Number	Device Name	PSID
825110-B21	HPE InfiniBand EDR/Ethernet 100Gb 1-port 840QSFP28 Adapter	HP_2180110032
825111-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 840QSFP28 Adapter	HP_2190110032
872726-B21	HPE InfiniBand EDR/Ethernet 100Gb 2-port 841QSFP28 Adapter	HPE0000000009
879482-B21	HPE InfiniBand FDR/Ethernet 40/50Gb 2-port 547FLR-QSFP Adapter	HPE0000000022

Online Firmware Upgrade Utility (ESXi 8.0) for Mellanox Open Ethernet cards

Version: 1.0.5 (**Recommended**)

Filename: CP063122.compsig; CP063122.zip

Important Note!

On Adapter Firmware rewrite scenario, SUM will always discover the Mellanox Open adapter firmware smart component as applicable and select it for deployment If the server iLO5 firmware version is older than 2.30.

Prerequisites

Use iLO5 firmware version 2.30 or higher with ConnectX4-Lx/ConnectX5 firmware version 14.32.1010/16.32.1010 respectively. Thermal sensor reporting on the adapter will not be functional with older versions of iLO5 firmware.

Fixes

No fixes have been included in firmware version 14.32.1900.

The following issues have been fixed in firmware version 16.35.4030:

- o VF FLR would get stuck when its PF triggered the FLR as well.
- o Unexpected source UDP port appeared in RoCE packets when the firmware ignored a non-PF driver configuration for RoCE source UDP port control (as set in SET_HCA_CAP.sw_r_roce_src_udp_port).

Enhancements

Firmware for the following devices has been updated to 14.32.1900:

- o P21930-B21 (HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCAT Adapter)
- o P11341-B21 (HPE Ethernet 10Gb 2-port SFP+ MCX4621A-ACAB OCP3 Adapter)

Firmware for the following device has been updated to 16.35.4030:

- o P21927-B21 (HPE Ethernet 100Gb 2-Port QSFP28 MCX516A-CCHT Adapter)

Security Hardening Enhancements

This release contains important reliability improvements and security hardening enhancements. NVIDIA recommends upgrading your devices firmware to this release to improve the devices' firmware security and reliability.

No new features or changes have been included in firmware version 14.32.1900.

New features and changes included in firmware version 16.35.4030:

- o Added support for postponing QP timeout "retry exceeded" errors for traffic directed at specific destinations. This new capability prevents broken connections for destinations in downtime because of live migration.

Supported Devices and Features

HPE Part Number	Mellanox Ethernet Only Adapters	PSID
P21930-B21	HPE Ethernet 10Gb 2-port SFP+ MCX4121A-XCHT Adapter	MT_0000000414
P11341-B21	HPE Ethernet 10Gb/25Gb 2-port SFP28 MCX4621A-ACAB OCP3 Adapter	MT_0000000238
P21927-B21	HPE Ethernet 100Gb 2-port QSFP28 MCX516A-CCHT Adapter	MT_0000000417

Firmware - Storage Controller

Controller Firmware Flash for ESXi8.0 and 9.0 - HPE MR216i-a Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (B) (**Recommended**)

Filename: CP066014.compsig; CP066014.zip

Enhancements

- o Support VMware ESXi 9.0.

Controller Firmware Flash for ESXi8.0 and 9.0 - HPE MR216i-p Gen10 Plus Tri Mode Controller

Version: 52.26.3.5487 (B) (**Recommended**)

Filename: CP066015.compsig; CP066015.zip

Enhancements

Support VMware ESXi 9.0.

Controller Firmware Flash for ESXi8.0 and 9.0 - HPE MR416i-a Gen10 Plus Tri Mode Controller
Version: 52.26.3.5487 (B) (**Recommended**)
Filename: CP066016.compsig; CP066016.zip

Enhancements

Support VMware ESXi 9.0.

Controller Firmware Flash for ESXi8.0 and 9.0 - HPE MR416i-p Gen10 Plus Tri Mode Controller
Version: 52.26.3.5487 (B) (**Recommended**)
Filename: CP066017.compsig; CP066017.zip

Enhancements

Support VMware ESXi 9.0.

Firmware Package - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P204i-c, P416ie-m and P816i-a SR Gen10 and SR308i-o,SR308i-p Gen11 controllers
Version: 7.43 (**Recommended**)
Filename: HPE_SR_Gen10_7.43_A.fwpgk

Fixes

- o Fixed an issue where a lockup occasionally occurs when RAID 0 Predictive Spare Rebuilding (PSR) starts.
- o Fixed an issue where the fault LED remains lit during the rebuild process of a replaced SSD drive.
- o Fixed an issue where the host was unable to retrieve new configuration updates after creating a logical drive on PF drives.
- o Fixed an issue where the logical volume status was incorrectly reported as OK on a secured volume if a data drive was replaced with an Otherwise Owned SED drive before reboot.
- o Fixed an issue where the surface scan period was not reset to default after factory reset.
- o Fixed an issue where the predictive failure drive did not fail even after the Predictive Spare Rebuild (PSR) was completed.
- o Fixed an issue where the Controller might have a potential lockup after a JBOD power cycle.
- o Fixed an issue where the offline replacement of a failed drive during a spare rebuild led to the failure of the replacement drive.
- o Fixed a lockup issue that could occur both during a transformation with an abrupt shutdown, and on subsequent bootup.
- o Fixed an intermittent MCTP communication issue during AC power cycle tests on specific configurations.
- o Fixed an MCTP communication issue in AMD Turin 2P configurations.
- o Fixed a lockup issue that could occur when a timeout occurs with expander attached SATA drives.
- o Fixed an issue with improper support checking for the secure erase command.
- o Fixed issues for missing active dedicated hot spare member in HII logical drive information and failed drive part of a logical drive in the HII disk utilities.
- o Fixed an issue which threw wrong error code, 'InternalError' when creating an array on controller that is waiting on adapter password.
- o Fixed an issue When server is powered on with no drives connected to Enclosure. Observe incorrect controller information in iLO Storage tab & Redfish
- o Fixed an issue that enclosures Link is missing under Storage URI in Redfish.
- o Fixed an issue in which drive resource does not match with Chassis for empty bay.
- o Fixed an issue in which incorrect severity warning of drive when sanitize erase operation is in progress.
- o Fixed an issue where HealthRollup shows warning during normal state.
- o Fixed an issue where CacheSummary.Status.Health shows incorrect during WriteCache degraded.
- o Fixed an issue in which PLDM/RDE Read sometimes take longer than 6s during array deletion.

Enhancements

- o PLDM Base (Type 0) commands comply with v1.2.0 of the PLDM base specification (DSP0240).
 - o PLDM Platform Monitoring and Control (Type 2) commands comply with v1.3.0 of the PLDM Platform Monitoring and Control Specification (DSP0248).
 - o Long-running task support for volume creation/deletion using Redfish and storage resource RDE action operations.
-

Firmware Package - HPE Gen11 Boot Controller NS204i-u, NS204i-d and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r
Version: 1.2.14.1018 (D) (**Recommended**)
Filename: HPE_NS204i_Gen10p_Gen11_1.2.14.1018_D.fwpgk; HPE_NS204i_Gen10p_Gen11_1.2.14.1018_D.json

Important Note!

1.2.14.1018 is the minimum firmware requirement for AMD Turin DL365/385 and Intel Gen12 platforms. Downgrading NS204i firmware to version lower than 1018 will lead to MCTP failure.

For Gen10 plus server users, the NS204i firmware has to be 1.0.14.1063 or later in order to enable PLDM firmware update functionality for the controller. Please find the smart component versions of 1.0.14.1063 in below link:

- o Windows: <https://www.hpe.com/global/swpublishing/MTX-be195b2891724ec8bb72c8bb2>
- o Linux: <https://www.hpe.com/global/swpublishing/MTX-269e14d0e2524277bf699f433>
- o Vmware: <https://www.hpe.com/global/swpublishing/MTX-1ffaca997cf248cd9f832a04c6>

Prerequisites

- o iLO 6 version 1.10 or later is required for Gen11 servers.
- o iLO 5 version 2.81 or later is required for Gen10/Gen10 Plus servers

Enhancements

- o Support new Gen 12 servers.
-

Firmware Package - HPE MR216i-a Gen10 Plus Tri Mode Controller
Version: 52.32.3-6118 (**Recommended**)

Important Note!

This new 7.32 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of July 2025.

- o **This firmware version to be used on HPE MR216i-a Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- o Fix a00147824en_us: HPE MR408i-p Gen11 Storage Controller - A False Error Message, "400 Bad Request," Indicates Reset Is Not Successful When Using the Redfish Command to Reset the Controller to Factory Default Settings
- o Fix a00143381en_us: HPE MR Gen10 Plus/Gen11 Controllers - A Predictive Failed Drive Fault Status LED Will Not Flash Amber As Expected When Configured As a JBOD
- o Fix an issue that imported secured drives in a span became unsecured
- o Filter drive spin-up sense prints to avoid flooding of log
- o Filter out underruns error prints to avoid flooding of TTY logs
- o Fix a rare issue that UBM backplane discovery fails, blocking the enclosure management state machine
- o Fix a rare timing issue that controller firmware asserts due to bar address change while still in device scanning state. Please note that updating from an old firmware version can still see the issue, since the issue happens when reset to activate new firmware.
- o Fix an issue that Logical Drive Status is not consistent while using the drive Hiding Options
- o Fix an issue that firmware may assert while doing full initialization on logical drive with NVME drives which have task management timeout
- o Fix a rare issue that firmware fault may occur when drive hotplug and Logical Drive property changes simultaneously
- o Fix a rare issue that data abort exception may occur when a physical drive is removed before enclosure or RDE (Redfish Device Enablement) module initialization is completed
- o Fix a rare issue that firmware fault may occur while controller reset with rebuild and PLDM type 0 in loop
- o Fix a rare issue that controller brick may happen if Task Management failure recovery reset in the middle of a firmware flashing sequence
- o Fix an issue that Cryptographic Erase option may be shown for a drive that does not support it. The issue happens when replacing a few Crypto-Erase-capable drives with drives that do not support Crypto Erase.
- o Fix an issue that SPDM is disabled when upgrading from firmware using Mbed TLS 2.6.12 to firmware using Mbed TLS 2.26.0+
- o Fix an issue that fails to enable local encryption with 255 characters in EncryptionKeyIdentifier property using Redfish. AllowablePattern is updated from {0, 255} to {1, 255}.
- o Fix an issue that Trim command shows as "Not supported" on NVMe 1.x drive.
- o Fix an issue that foreign configuration import is not accessible from RDE after reboot
- o Fix a rare timing issue that Cache Offload failed with error No offload detected
- o Fix a rare issue that firmware may assert while running firmware update when the bootloaders in two firmwares are different versions.
- o Redfish None Type Volume created with "Encrypted" property should not be allowed to POST
- o Fix an issue that VM with PCIe passthrough configuration fails to bootup after a host reboot on Linux hypervisor
- o Fix an issue that Request Sense command causes task management on the drive where sanitization is in progress.

Enhancements

- o DMTF PLDM Redfish Device Enablement enhancements
 - o Redfish Compliance to 2024.2 Schema Bundle
 - o Updated the dictionary to the 2024.2 schema bundle
 - o GET/PATCH StorageController[AssetTag]
 - o GET/PATCH Storage.HotspareActivationPolicy
 - Note: The Storage.HotspareActivationPolicy is modifiable only when the Copyback feature is enabled in FW. By default, Copyback feature is turned on along with smarthdd and smartssd. User can disable the Copyback feature from storcli. To enable or disable the Copyback feature, see "storcli /cx set copyback" details in the MR SW user guide.
 - o GET Drive[DriveFormFactor], [SlotCapableProtocols], [FirmwareVersion]
 - Note: DriveFormFactor is not supported for the NVMe drives as the method for arriving at the form factor is not currently supported.
 - o GET Port[PortProtocol], [PortType]
 - o EKM Rekey support
 - o POST #Storage.RekeyExternalKey Action from the Storage Schema.
 - o Reboot the server to obtain the new EKM Key from UEFI driver.
 - o Added support for WriteCacheDegraded Redfish Alert and correct CacheSummary State and Health for Pinned Cache scenario (Data trapped in cache).
 - o This improvement resolves a00143111en_us: HPE MR Gen11 and Gen10 Plus Controllers - Logical Drive Functions May be Blocked Unexpectedly Without IML Notification
- o Increased Frequency of Temperature Polling for NVMe Drives
 - o Default value is set to 15 seconds
 - o The parameter can be queried and configured using StorCLI
- o Second Source NAND Flash
 - o Controller firmware downgrades to below 7.26 (PR3 or earlier) are blocked on a controller using second source NAND flash.
 - o The first source NAND flash size is 23.625 GB; the second source NAND flash size is 21.301 GB. This information can be obtained from "CacheVault Flash Size" parameter in the "storcli /cx show all" command.
- o Add support for NVMe 2.0 drives
- o When an NVMe drive is being initialized using Write Same command, check against the max write same length from VPD B0.
- o Add support for enable/disable controller phys
 - o Use storcli /cx/px set state= <on|off> to enable/disable controller phys
- o Keep Locate LED state when a JBOD drive transitions to Unconfigured Good
- o Added support for reporting Gen 5 physical disk speed

- o Support for SCSI NVMe Translation Layer Specification version 1.15
- o Enhance Smart Poll Failures
 - o Per physical drive tracker is added to identify if the drive supported smart poll feature in its lifetime.
 - o If the drive supported the feature and for any reason smart poll fails, previously reported temperature is not overwritten, and smart poll is retried in next cycle.
 - o On the drives, where SCSI format command is pending, changes are made to try smart poll in next cycle.
 - o Smart polling is skipped on physical drives, where drive erase or sanitize operation is in progress.
- o Set physical drive media type to unknown when the drive is misbehaving
- o Improve the handle for simultaneous single and double ECC errors. Ensure uncorrectable errors halt system boot and appropriate alerts are raised.
- o Improve handling of malformed/invalid/bad CDBs.
 - o Check SGEs (Scatter-Gather Element) and data lengths are non-zero for Read/Write CDBs with non-zero block count to ensure controller does not hit DMA errors.
 - o Check and fail command for out of bound access scenarios for certain non- Read/Write commands like Mode Select which could cause controller exceptions by accessing memory out of bounds.

Firmware Package - HPE MR216i-p Gen10 Plus Tri Mode Controller
 Version: 52.32.3-6118 (**Recommended**)
 Filename: HPE_MR216i-p_Gen10P_52.32.3-6118_A.fwpkg

Important Note!

This new 7.32 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of July 2025.

- o **This firmware version to be used on HPE MR216i-p Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- o Fix a00147824en_us: HPE MR408i-p Gen11 Storage Controller - A False Error Message, "400 Bad Request," Indicates Reset Is Not Successful When Using the Redfish Command to Reset the Controller to Factory Default Settings
- o Fix a00143381en_us: HPE MR Gen10 Plus/Gen11 Controllers - A Predictive Failed Drive Fault Status LED Will Not Flash Amber As Expected When Configured As a JBOD
- o Fix an issue that imported secured drives in a span became unsecured
- o Filter drive spin-up sense prints to avoid flooding of log
- o Filter out underruns error prints to avoid flooding of TTY logs
- o Fix a rare issue that UBM backplane discovery fails, blocking the enclosure management state machine
- o Fix a rare timing issue that controller firmware asserts due to bar address change while still in device scanning state. Please note that updating from an old firmware version can still see the issue, since the issue happens when reset to activate new firmware.
- o Fix an issue that Logical Drive Status is not consistent while using the drive Hiding Options
- o Fix an issue that firmware may assert while doing full initialization on logical drive with NVME drives which have task management timeout
- o Fix a rare issue that firmware fault may occur when drive hotplug and Logical Drive property changes simultaneously
- o Fix a rare issue that data abort exception may occur when a physical drive is removed before enclosure or RDE (Redfish Device Enablement) module initialization is completed
- o Fix a rare issue that firmware fault may occur while controller reset with rebuild and PLDM type 0 in loop
- o Fix a rare issue that controller brick may happen if Task Management failure recovery reset in the middle of a firmware flashing sequence
- o Fix an issue that Cryptographic Erase option may be shown for a drive that does not support it. The issue happens when replacing a few Crypto-Erase-capable drives with drives that do not support Crypto Erase.
- o Fix an issue that SPDM is disabled when upgrading from firmware using Mbed TLS 2.6.12 to firmware using Mbed TLS 2.26.0+
- o Fix an issue that fails to enable local encryption with 255 characters in EncryptionKeyIdentifier property using Redfish. AllowablePattern is updated from {0, 255} to {1, 255}.
- o Fix an issue that Trim command shows as "Not supported" on NVMe 1.x drive.
- o Fix an issue that foreign configuration import is not accessible from RDE after reboot
- o Fix a rare timing issue that Cache Offload failed with error No offload detected
- o Fix a rare issue that firmware may assert while running firmware update when the bootloaders in two firmwares are different versions.
- o Redfish None Type Volume created with "Encrypted" property should not be allowed to POST
- o Fix an issue that VM with PCIe passthrough configuration fails to bootup after a host reboot on Linux hypervisor
- o Fix an issue that Request Sense command causes task management on the drive where sanitization is in progress.

Enhancements

- o DMTF PLDM Redfish Device Enablement enhancements
 - o Redfish Compliance to 2024.2 Schema Bundle
 - o Updated the dictionary to the 2024.2 schema bundle
 - o GET/PATCH StorageController[AssetTag]
 - o GET/PATCH Storage.HotspareActivationPolicy
 - Note: The Storage.HotspareActivationPolicy is modifiable only when the Copyback feature is enabled in FW. By default, Copyback feature is turned on along with smarthdd and smartssd. User can disable the Copyback feature from storcli. To enable or disable the Copyback feature, see "storcli /cx set copyback" details in the MR SW user guide.
 - o GET Drive[DriveFormFactor], [SlotCapableProtocols], [FirmwareVersion]
 - Note: DriveFormFactor is not supported for the NVMe drives as the method for arriving at the form factor is not currently supported.
 - o GET Port[PortProtocol], [PortType]
 - o EKM Rekey support
- o POST #Storage.RekeyExternalKey Action from the Storage Schema.
- o Reboot the server to obtain the new EKM Key from UEFI driver.

- o Added support for WriteCacheDegraded Redfish Alert and correct CacheSummary State and Health for Pinned Cache scenario (Data trapped in cache).
- o This improvement resolves a00143111en_us: HPE MR Gen11 and Gen10 Plus Controllers - Logical Drive Functions May be Blocked Unexpectedly Without IML Notification
- o Increased Frequency of Temperature Polling for NVMe Drives
 - o Default value is set to 15 seconds
 - o The parameter can be queried and configured using StorCLI
- o Second Source NAND Flash
 - o Controller firmware downgrades to below 7.26 (PR3 or earlier) are blocked on a controller using second source NAND flash.
 - o The first source NAND flash size is 23.625 GB; the second source NAND flash size is 21.301 GB. This information can be obtained from "CacheVault Flash Size" parameter in the "storcli /cx show all" command.
- o Add support for NVMe 2.0 drives
- o When an NVMe drive is being initialized using Write Same command, check against the max write same length from VPD B0.
- o Add support for enable/disable controller phys
 - o Use storcli /cx/px set state= <on|off> to enable/disable controller phys
- o Keep Locate LED state when a JBOD drive transitions to Unconfigured Good
- o Added support for reporting Gen 5 physical disk speed
- o Support for SCSI NVMe Translation Layer Specification version 1.15
- o Enhance Smart Poll Failures
 - o Per physical drive tracker is added to identify if the drive supported smart poll feature in its lifetime.
 - o If the drive supported the feature and for any reason smart poll fails, previously reported temperature is not overwritten, and smart poll is retried in next cycle.
 - o On the drives, where SCSI format command is pending, changes are made to try smart poll in next cycle.
 - o Smart polling is skipped on physical drives, where drive erase or sanitize operation is in progress.
- o Set physical drive media type to unknown when the drive is misbehaving
- o Improve the handle for simultaneous single and double ECC errors. Ensure uncorrectable errors halt system boot and appropriate alerts are raised.
- o Improve handling of malformed/invalid/bad CDBs.
 - o Check SGEs (Scatter-Gather Element) and data lengths are non-zero for Read/Write CDBs with non-zero block count to ensure controller does not hit DMA errors.
 - o Check and fail command for out of bound access scenarios for certain non- Read/Write commands like Mode Select which could cause controller exceptions by accessing memory out of bounds.

Firmware Package - HPE MR416i-a Gen10 Plus Tri Mode Controller
 Version: 52.32.3-6118 (**Recommended**)
 Filename: HPE_MR416i-a_Gen10P_52.32.3-6118_A.fwpgk

Important Note!

This new 7.32 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of July 2025.

- o **This firmware version to be used on HPE MR416i-a Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- o Fix a00147824en_us: HPE MR408i-p Gen11 Storage Controller - A False Error Message, "400 Bad Request," Indicates Reset Is Not Successful When Using the Redfish Command to Reset the Controller to Factory Default Settings
- o Fix a00143381en_us: HPE MR Gen10 Plus/Gen11 Controllers - A Predictive Failed Drive Fault Status LED Will Not Flash Amber As Expected When Configured As a JBOD
- o Fix an issue that imported secured drives in a span became unsecured
- o Filter drive spin-up sense prints to avoid flooding of log
- o Filter out underruns error prints to avoid flooding of TTY logs
- o Fix a rare issue that UBM backplane discovery fails, blocking the enclosure management state machine
- o Fix a rare timing issue that controller firmware asserts due to bar address change while still in device scanning state. Please note that updating from an old firmware version can still see the issue, since the issue happens when reset to activate new firmware.
- o Fix an issue that Logical Drive Status is not consistent while using the drive Hiding Options
- o Fix an issue that firmware may assert while doing full initialization on logical drive with NVME drives which have task management timeout
- o Fix a rare issue that firmware fault may occur when drive hotplug and Logical Drive property changes simultaneously
- o Fix a rare issue that data abort exception may occur when a physical drive is removed before enclosure or RDE (Redfish Device Enablement) module initialization is completed
- o Fix a rare issue that firmware fault may occur while controller reset with rebuild and PLDM type 0 in loop
- o Fix a rare issue that controller brick may happen if Task Management failure recovery reset in the middle of a firmware flashing sequence
- o Fix an issue that Cryptographic Erase option may be shown for a drive that does not support it. The issue happens when replacing a few Crypto-Erase-capable drives with drives that do not support Crypto Erase.
- o Fix an issue that SPDM is disabled when upgrading from firmware using Mbed TLS 2.6.12 to firmware using Mbed TLS 2.26.0+
- o Fix an issue that fails to enable local encryption with 255 characters in EncryptionKeyIdentifier property using Redfish. AllowablePattern is updated from {0, 255} to {1, 255}.
- o Fix an issue that Trim command shows as "Not supported" on NVMe 1.x drive.
- o Fix an issue that foreign configuration import is not accessible from RDE after reboot
- o Fix a rare timing issue that Cache Offload failed with error No offload detected
- o Fix a rare issue that firmware may assert while running firmware update when the bootloaders in two firmwares are different versions.
- o Redfish None Type Volume created with "Encrypted" property should not be allowed to POST
- o Fix an issue that VM with PCIe passthrough configuration fails to bootup after a host reboot on Linux hypervisor
- o Fix an issue that Request Sense command causes task management on the drive where sanitization is in progress.

Enhancements

- o DMTF PLDM Redfish Device Enablement enhancements
 - o Redfish Compliance to 2024.2 Schema Bundle

- o Updated the dictionary to the 2024.2 schema bundle
- o GET/PATCH StorageController[AssetTag]
- o GET/PATCH Storage.HotspareActivationPolicy

Note: The Storage.HotspareActivationPolicy is modifiable only when the Copyback feature is enabled in FW. By default, Copyback feature is turned on along with smarthdd and smartssd. User can disable the Copyback feature from storcli. To enable or disable the Copyback feature, see "storcli /cx set copyback" details in the MR SW user guide.

- o GET Drive[DriveFormFactor], [SlotCapableProtocols], [FirmwareVersion]

Note: DriveFormFactor is not supported for the NVMe drives as the method for arriving at the form factor is not currently supported.

- o GET Port[PortProtocol], [PortType]

o EKM Rekey support

- o POST #Storage.RekeyExternalKey Action from the Storage Schema.
- o Reboot the server to obtain the new EKM Key from UEFI driver.

o Added support for WriteCacheDegraded Redfish Alert and correct CacheSummary State and Health for Pinned Cache scenario (Data trapped in cache).

- o This improvement resolves a00143111en_us: HPE MR Gen11 and Gen10 Plus Controllers - Logical Drive Functions May be Blocked Unexpectedly Without IML Notification

o Increased Frequency of Temperature Polling for NVMe Drives

- o Default value is set to 15 seconds
- o The parameter can be queried and configured using StorCLI

o Second Source NAND Flash

- o Controller firmware downgrades to below 7.26 (PR3 or earlier) are blocked on a controller using second source NAND flash.
- o The first source NAND flash size is 23.625 GB; the second source NAND flash size is 21.301 GB. This information can be obtained from "CacheVault Flash Size" parameter in the "storcli /cx show all" command.

o Add support for NVMe 2.0 drives

- o When an NVMe drive is being initialized using Write Same command, check against the max write same length from VPD B0.

o Add support for enable/disable controller phys

- o Use storcli /cx/px set state= <on|off> to enable/disable controller phys

o Keep Locate LED state when a JBOD drive transitions to Unconfigured Good

o Added support for reporting Gen 5 physical disk speed

o Support for SCSI NVMe Translation Layer Specification version 1.15

o Enhance Smart Poll Failures

- o Per physical drive tracker is added to identify if the drive supported smart poll feature in its lifetime.
- o If the drive supported the feature and for any reason smart poll fails, previously reported temperature is not overwritten, and smart poll is retried in next cycle.
- o On the drives, where SCSI format command is pending, changes are made to try smart poll in next cycle.
- o Smart polling is skipped on physical drives, where drive erase or sanitize operation is in progress.

o Set physical drive media type to unknown when the drive is misbehaving

o Improve the handle for simultaneous single and double ECC errors. Ensure uncorrectable errors halt system boot and appropriate alerts are raised.

o Improve handling of malformed/invalid/bad CDBs.

- o Check SGEs (Scatter-Gather Element) and data lengths are non-zero for Read/Write CDBs with non-zero block count to ensure controller does not hit DMA errors.

- o Check and fail command for out of bound access scenarios for certain non- Read/Write commands like Mode Select which could cause controller exceptions by accessing memory out of bounds.

Firmware Package - HPE MR416i-p Gen10 Plus Tri Mode Controller

Version: 52.32.3-6118 (**Recommended**)

Filename: HPE_MR416i-p_Gen10P_52.32.3-6118_A.fwpgk

Important Note!

This new 7.32 release have not completed vSAN certification, please don't update for vSAN environment for now. Target to complete vSAN certification by end of July 2025.

- o **This firmware version to be used on HPE MR416i-p Gen10 Plus Controller.**

Prerequisites

iLO5 version should be at least 2.98 is required for **chassis&Fabric support**.

Fixes

- o Fix a00147824en_us: HPE MR408i-p Gen11 Storage Controller - A False Error Message, "400 Bad Request," Indicates Reset Is Not Successful When Using the Redfish Command to Reset the Controller to Factory Default Settings
- o Fix a00143381en_us: HPE MR Gen10 Plus/Gen11 Controllers - A Predictive Failed Drive Fault Status LED Will Not Flash Amber As Expected When Configured As a JBOD
- o Fix an issue that imported secured drives in a span became unsecured
- o Filter drive spin-up sense prints to avoid flooding of log
- o Filter out underruns error prints to avoid flooding of TTY logs
- o Fix a rare issue that UBM backplane discovery fails, blocking the enclosure management state machine
- o Fix a rare timing issue that controller firmware asserts due to bar address change while still in device scanning state. Please note that updating from an old firmware version can still see the issue, since the issue happens when reset to activate new firmware.
- o Fix an issue that Logical Drive Status is not consistent while using the drive Hiding Options
- o Fix an issue that firmware may assert while doing full initialization on logical drive with NVMe drives which have task management timeout
- o Fix a rare issue that firmware fault may occur when drive hotplug and Logical Drive property changes simultaneously

- o Fix a rare issue that data abort exception may occur when a physical drive is removed before enclosure or RDE (Redfish Device Enablement) module initialization is completed
- o Fix a rare issue that firmware fault may occur while controller reset with rebuild and PLDM type 0 in loop
- o Fix a rare issue that controller brick may happen if Task Management failure recovery reset in the middle of a firmware flashing sequence
- o Fix an issue that Cryptographic Erase option may be shown for a drive that does not support it. The issue happens when replacing a few Crypto-Erase-capable drives with drives that do not support Crypto Erase.
- o Fix an issue that SPDm is disabled when upgrading from firmware using Mbed TLS 2.6.12 to firmware using Mbed TLS 2.26.0+
- o Fix an issue that fails to enable local encryption with 255 characters in EncryptionKeyIdentifier property using Redfish. AllowablePattern is updated from {0, 255} to {1, 255}.
- o Fix an issue that Trim command shows as "Not supported" on NVMe 1.x drive.
- o Fix an issue that foreign configuration import is not accessible from RDE after reboot
- o Fix a rare timing issue that Cache Offload failed with error No offload detected
- o Fix a rare issue that firmware may assert while running firmware update when the bootloaders in two firmwares are different versions.
- o Redfish None Type Volume created with "Encrypted" property should not be allowed to POST
- o Fix an issue that VM with PCIe passthrough configuration fails to bootup after a host reboot on Linux hypervisor
- o Fix an issue that Request Sense command causes task management on the drive where sanitization is in progress.

Enhancements

- o DMTF PLDM Redfish Device Enablement enhancements
 - o Redfish Compliance to 2024.2 Schema Bundle
 - o Updated the dictionary to the 2024.2 schema bundle
 - o GET/PATCH StorageController[AssetTag]
 - o GET/PATCH Storage.HotspareActivationPolicy
 - Note: The Storage.HotspareActivationPolicy is modifiable only when the Copyback feature is enabled in FW. By default, Copyback feature is turned on along with smarthdd and smartssd. User can disable the Copyback feature with storcli. To enable or disable the Copyback feature, see "storcli /cx set copyback" details in the MR SW user guide.
 - o GET Drive[DriveFormFactor], [SlotCapableProtocols], [FirmwareVersion]
 - Note: DriveFormFactor is not supported for the NVMe drives as the method for arriving at the form factor is not currently supported.
 - o GET Port[PortProtocol], [PortType]
 - o EKM Rekey support
 - o POST #Storage.RekeyExternalKey Action from the Storage Schema.
 - o Reboot the server to obtain the new EKM Key from UEFI driver.
 - o Added support for WriteCacheDegraded Redfish Alert and correct CacheSummary State and Health for Pinned Cache scenario (Data trapped in cache).
 - o This improvement resolves a00143111en_us: HPE MR Gen11 and Gen10 Plus Controllers - Logical Drive Functions May be Blocked Unexpectedly Without IML Notification
- o Increased Frequency of Temperature Polling for NVMe Drives
 - o Default value is set to 15 seconds
 - o The parameter can be queried and configured using StorCLI
- o Second Source NAND Flash
 - o Controller firmware downgrades to below 7.26 (PR3 or earlier) are blocked on a controller using second source NAND flash.
 - o The first source NAND flash size is 23.625 GB; the second source NAND flash size is 21.301 GB. This information can be obtained from "CacheVault Flash Size" parameter in the "storcli /cx show all" command.
- o Add support for NVMe 2.0 drives
- o When an NVMe drive is being initialized using Write Same Command, check against the max write same length from VPD B0.
- o Add support for enable/disable controller phys
 - o Use storcli /cx/px set state= <on|off> to enable/disable controller phys
- o Keep Locate LED state when a JBOD drive transitions to Unconfigured Good
- o Added support for reporting Gen 5 physical disk speed
- o Support for SCSI NVMe Translation Layer Specification version 1.15
- o Enhance Smart Poll Failures
 - o Per physical drive tracker is added to identify if the drive supported smart poll feature in its lifetime.
 - o If the drive supported the feature and for any reason smart poll fails, previously reported temperature is not overwritten, and smart poll is retried in next cycle.
 - o On the drives, where SCSI format command is pending, changes are made to try smart poll in next cycle.
 - o Smart polling is skipped on physical drives, where drive erase or sanitize operation is in progress.
- o Set physical drive media type to unknown when the drive is misbehaving
- o Improve the handle for simultaneous single and double ECC errors. Ensure uncorrectable errors halt system boot and appropriate alerts are raised.
- o Improve handling of malformed/invalid/bad CDBs.
 - o Check SGEs (Scatter-Gather Element) and data lengths are non-zero for Read/Write CDBs with non-zero block count to ensure controller does not hit DMA errors.
 - o Check and fail command for out of bound access scenarios for certain non- Read/Write commands like Mode Select which could cause controller exceptions by accessing memory out of bounds.

Firmware Package - HPE SR932i-p Gen10 Plus /SR416i-a Gen10 Plus/SR932i-p Gen11/SR416ie-m Gen11 Controllers
 Version: 03.01.33.044 **(Recommended)**
 Filename: HPE_SR416_SR932_Gen10P_Gen11_03.01.33.044_A.fwpkg

Fixes

- o Fixed an issue where a lockup occasionally occurs when RAID 0 Predictive Spare Rebuilding (PSR) starts.
- o Fixed an issue where the fault LED remains lit during the rebuild process of a replaced SSD drive.

- o Fixed an issue where the host was unable to retrieve new configuration updates after creating a logical drive on PF drives or slow drives.
- o Fixed an issue where the logical volume status was incorrectly reported as OK on a secured volume if a data drive was replaced with an Otherwise Owned SED drive before reboot.
- o Fixed an issue where the surface scan period was not reset to default after factory reset.
- o Fixed an issue where the predictive failure drive did not fail even after the Predictive Spare Rebuild (PSR) was completed.
- o Fixed an issue where the Controller might have a potential lockup after a JBOD power cycle.
- o Fixed an issue where the offline replacement of a failed drive during a spare rebuild led to the failure of the replacement drive.
- o Fixed a possible lockup that could occur both during a transformation with an abrupt shutdown, and on subsequent bootup.
- o Fixed a potential issue where a good drive could be incorrectly marked as a predictive failure drive.
- o Fixed a lockup issue that could occur during I/O to a degraded volume using Smart Path.
- o Fixed a drive firmware update failure due to incorrect handling of sense data for specific SATA drives.
- o Fixed a Controller boot failure when inserted in PCIe Gen 6 systems.
- o Fixed issues for missing active dedicated hot spare member in HII logical drive information and failed drive part of a logical drive in the HII disk utilities.
- o Fixed an issue which threw wrong error code, 'InternalError' when creating an array on controller that is waiting on adapter password.
- o Fixed an issue When server is powered on with no drives connected to Enclosure. Observe incorrect controller information in iLO Storage tab & Redfish
- o Fixed an issue that enclosures Link is missing under Storage URI in Redfish.
- o Fixed an issue in which drive resource does not match with Chassis for empty bay.
- o Fixed an issue in which incorrect severity warning of drive when sanitize erase operation is in progress.
- o Fixed an issue where HealthRollup shows warning during normal state.
- o Fixed an issue where CacheSummary.Status.Health shows incorrect during WriteCache degraded.
- o Fixed an issue in which PLDM/RDE Read sometimes take longer than 6s during array deletion.

Enhancements

- o PLDM Base (Type 0) commands comply with v1.2.0 of the PLDM base specification (DSP0240).
- o PLDM Platform Monitoring and Control (Type 2) commands comply with v1.3.0 of the PLDM Platform Monitoring and Control Specification (DSP0248).
- o Long-running task support for volume creation/deletion using Redfish and storage resource RDE action operations.

HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)
Version: 5.04 (L) (**Recommended**)
Filename: CP066421.compsig; CP066421.md5; CP066421.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- o The Enabled-ClusterS2D command now completes successfully when executed on a SATA drive within a D3610 disk enclosure for a NonStop solution.
- o The smart carrier, which is the drive case for SAS drives, now authenticates in the D3610/D3710 drive enclosure.
- o Added new 7-segment error codes E0 and E1 to report issues with Fan modules A and B, respectively. These new codes only apply to the D3610/D3710 and only display when running firmware 5.04.
- o If the storage enclosure processor within the I/O module fails, a hard reset (power down and then power up) is executed to ensure the processor comes back online.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 9.0

Removed support of ESXi 7.0

Supported Devices and Features

The D3600 / D3700 / D3610 / D3710 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- o Smart Array P408e-p Controller
- o Smart Array E208e-p Controller

HPE D3610B/D3710B 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 6.00 (F) (**Recommended**)

Filename: CP066424.compsig; CP066424.md5; CP066424.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D3000B(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000B.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- o Code optimization to save memory repo.
- o TLB exception seen while doing esp reset when expander reset was in progress.
- o Added the psoc 8.93 binary in peripheral images, updated the reveille version numbers.
- o Added whole new Delta PS-pmbus code , Updated the ESP version number.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

Added support of ESXi 9.0

Removed support of ESXi 7.0

Supported Devices and Features

The D3610B / D3710B Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- o Smart Array P408e-p Controller
- o Smart Array E208e-p Controller

HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)

Version: 2.74 (S) (**Recommended**)

Filename: CP066427.compsig; CP066427.md5; CP066427.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D6020(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D6020.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- o Temperature sensors logic inside gSEP model and SES database
- o When an IOM is pulled the surviving IOM reports false critical temperatures

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

- Added support of ESXi 9.0
- Removed support of ESXi 7.0

Supported Devices and Features

The D6020 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- o Smart Array P408e-p Controller
- o Smart Array E208e-p Controller

HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)
Version: 0130 (G) (**Recommended**)
Filename: CP066430.compsig; CP066430.md5; CP066430.zip

Important Note!

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted. In single domain configuration, if user hosts an OS in D8000(or any storage box) and flash the SEPs, it will hang/crash everytime as SmartComponent will reset the SEPs after flash/codeload.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to /var/cpq/Component.log.

Prerequisites

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D8000.log and flash summary is logged to /var/cpq/Component.log.

Fixes

The following fixes were incorporated in this version:

- o Smart Array reporting "Storage Enclosure FW upgrade Problem Detected".
- o PSU version is showing as "No Ver" after inserted the New bel power PSU.
- o GEM_5_2 Coverity defect fix.

Please refer to the [Release Notes](#) for the complete listing of fixes, enhancements, known issues and work-arounds corresponding to this firmware.

Enhancements

- Added support of ESXi 9.0
- Removed support of ESXi 7.0

Supported Devices and Features

The D8000 Enclosure can be attached to any of the following HPE Storage Controllers and Host Bus Adapters :

- o HPE Smart Array P408e-p Controller
- o HPE Smart Array E208e-p Controller

Online Firmware Flash for ESXi - HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-r, NS204i-u and NS204i-d Gen11
Version: 1.0.14.1063 (C) (**Recommended**)
Filename: CP064740.compsig; CP064740.zip

Important Note!

- o **This version is the minimum required version for Gen10 Plus device to upgrade to latest FW**
- o **You can get Firmware Package version 1.2.14.1004 or latest FW version from <https://www.hpe.com/global/swpublishing/MTX-318c8e8298704d8bb4f991eb4d> and update it via iLO without any OS dependency.**

Enhancements

- o Added ESXi9.0 support.

Online ROM Flash Component for VMware ESXi - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers
Version: 5.15 (C) (**Recommended**)
Filename: CP064922.compsig; CP064922.zip

Important Note!

- o **Do NOT downgrade FW to previous version if your current expander is 5.10; please upgrade to 5.15 immediately.**

Enhancements

- o Added ESXi9.0 support.

Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Plus Backplane Expander FW
Version: 1.27 (C) (**Recommended**)
Filename: CP064920.compsig; CP064920.zip

Enhancements

- o Added ESXi9.0 support.

Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Gen10 Plus Backplane Expander Firmware
Version: 0.39 (D) (**Recommended**)
Filename: CP064921.compsig; CP064921.zip

Prerequisites

- o Before upgrading to 0.39(D), please flash to the transition version 0.39 first by standalone update approach to activate the new PID naming.
- o 0.39(B) is the minimum version for Gen10plus 4200 expander FW.
- o **0.39 transition version link:** <https://www.hpe.com/global/swpublishing/MTX-baec686eb389427aa933bbf9f0>

Enhancements

- o Support ESXi9.0 OS.

Online ROM Flash Component for VMware ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, E208i-p, E208e-p, E208i-a, P816i-a SR Gen10 Controllers
Version: 7.43 (**Recommended**)
Filename: CP062902.compsig; CP062902.zip

Fixes

- o Fixed an issue where a lockup occasionally occurs when RAID 0 Predictive Spare Rebuilding (PSR) starts.
- o Fixed an issue where the fault LED remains lit during the rebuild process of a replaced SSD drive.
- o Fixed an issue where the host was unable to retrieve new configuration updates after creating a logical drive on PF drives.
- o Fixed an issue where the logical volume status was incorrectly reported as OK on a secured volume if a data drive was replaced with an Otherwise Owned SED drive before reboot.
- o Fixed an issue where the surface scan period was not reset to default after factory reset.
- o Fixed an issue where the predictive failure drive did not fail even after the Predictive Spare Rebuild (PSR) was completed.
- o Fixed an issue where the Controller might have a potential lockup after a JBOD power cycle.
- o Fixed an issue where the offline replacement of a failed drive during a spare rebuild led to the failure of the replacement drive.
- o Fixed a lockup issue that could occur both during a transformation with an abrupt shutdown, and on subsequent bootup.
- o Fixed an intermittent MCTP communication issue during AC power cycle tests on specific configurations.
- o Fixed an MCTP communication issue in AMD Turin 2P configurations.
- o Fixed a lockup issue that could occur when a timeout occurs with expander attached SATA drives.
- o Fixed an issue with improper support checking for the secure erase command.
- o Fixed issues for missing active dedicated hot spare member in HII logical drive information and failed drive part of a logical drive in the HII disk utilities.
- o Fixed an issue which threw wrong error code, 'InternalError' when creating an array on controller that is waiting on adapter password.
- o Fixed an issue When server is powered on with no drives connected to Enclosure. Observe incorrect controller information in iLO Storage tab & Redfish
- o Fixed an issue that enclosures Link is missing under Storage URI in Redfish.
- o Fixed an issue in which drive resource does not match with Chassis for empty bay.
- o Fixed an issue in which incorrect severity warning of drive when sanitize erase operation is in progress.
- o Fixed an issue where HealthRollup shows warning during normal state.
- o Fixed an issue where CacheSummary.Status.Health shows incorrect during WriteCache degraded.
- o Fixed an issue in which PLDM/RDE Read sometimes take longer than 6s during array deletion.

Enhancements

- o PLDM Base (Type 0) commands comply with v1.2.0 of the PLDM base specification (DSP0240).
- o PLDM Platform Monitoring and Control (Type 2) commands comply with v1.3.0 of the PLDM Platform Monitoring and Control Specification (DSP0248).
- o Long-running task support for volume creation/deletion using Redfish and storage resource RDE action operations.

Online ROM Flash Component for VMware ESXi - HPE Smart Array P816i-a,P416ie-m,P408i-p, P408e-p, P408i-a,P408i-c,P204i-c,E208i-p, E208e-p, E208i-a, P208i-c SR Gen10
Version: 5.61 (E) (**Recommended**)
Filename: CP064739.compsig; CP064739.zip

Enhancements

- o Added ESXi9.0 support.

Firmware - Storage Fibre Channel

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 8.0
Version: 2025.03.01 (**Recommended**)
Filename: CP063477.compsig; CP063477.zip

[Top](#)

Important Note!

Release notes:

[Broadcom Release notes](#)

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	Boot Bios
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0

HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	Boot Bios
HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter	16Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter	16Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.4.473.14	14.4.473.14	14.4.473.8	14.4.469.0

Supported Devices and Features

This component is supported on following Emulex Fibre Channel Host Bus adapters:

16Gb FC Adapter:

- HPE SN1200E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1200E 16Gb Single Port Fibre Channel Host Bus Adapter

32Gb FC Adapter:

- HPE SN1600E 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1600E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Single port Fibre Channel Host Bus Adapter

64Gb FC Adapter:

- HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter

HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 8.0

Version: 2025.05.02 (**Recommended**)

Filename: CP067635.compsig; CP067635.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This Firmware package contains following firmware versions:

Adapter	Speed	MBI	Firmware	UEFI	Boot Bios
HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	02.11.01	09.15.05	7.39	0.0

Fixed the following:

1. Windows BitLocker causes the system boot due to ROM signature failure during POST.
2. Increase an internal timeout value for SPI/Flash read.

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Fixes

Fixed the following:

1. Windows BitLocker causes the system boot due to ROM signature failure during POST.
2. Increase an internal timeout value for SPI/Flash read.

Enhancements

This Firmware package contains following firmware versions:

Adapter	Speed	MBI	Firmware	UEFI	Boot Bios
HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter	16Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.05.01	9.15.05	7.28	3.68
HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	02.11.01	09.15.05	7.39	0.0
HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	02.11.01	09.15.05	7.39	0.0

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- o HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- o HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- o HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- o HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- o HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

Software - Management

HPE iLO Driver Bundle Smart Component for ESXi 8.0 and ESXi 9.0
Version: 2025.03.00 (**Recommended**)
Filename: cp064439.compsig; cp064439.zip

[Top](#)

Enhancements

Support VMware ESXi 9.0.

Smart Storage Administrator (SSA) CLI Smart Component for ESXi 8.0 for Gen10/Gen10 Plus/Gen11 Controllers
Version: 2025.02.01 (**Recommended**)
Filename: cp062924.compsig; cp062924.zip

Important Note!

- o Actual ESXi ssacli version is 6.45.8.0

Fixes

- o Corrected wrong wording of Parity Initialization messages.
- o Fixed vulnerability CVE-2023-45853.

Enhancements

- o Added Write Cache Status field to the info page for physical drives when "pd all show detail" is used.

Software - Storage Controller

HPE MegaRAID Storage Administrator StorCLI for VMware8.0 (For Gen10P and Gen11 Controllers)
Version: 2025.05.01 (**Recommended**)
Filename: cp064826.compsig; cp064826.zip

[Top](#)

Important Note!

- o Actual ESXi Version is 007.3210.0000.0000

Enhancements

- o Increase the frequency of temperature polling for NVMe drives. Use the following commands to show or set the option.
 - storcli /cx show nvmeThermalPollInterval
 - storcli /cx set nvmeThermalPollInterval=<value>
- o Add max drive rate (32 GTPS) display for Gen 5 Drive
- o Support Drive makers authority in storcli
 - If the support bit is set displaying new property "Makers Authority Enabled" in drive details show all command
- o Physical Disk type Unknown for cases where Physical Drive is misbehaving
- o Enhanced Firmware logging during Boot. Use the following commands to show or set the option.
 - storcli /cx show inactivityprint
 - storcli /cx set inactivityprint=<on|off>
- o Update the readme and license file
- o Controller show all command (storcli /cx show all) lists "Power Saving option = Enable"
- o Support for Link isolation power savings. Add below command to enable/disable a phy.
 - storcli /cx/px set state=<on|off>
- o Remove DimmerSwitch option from storcli
- o Terminology alignment for REFCLK/PERST
 - Refclk property name is changed to "PCIe Reference Clock"
 - Perst output string are changed to : 0 - Default (No Override), 1 - Deasserted, 2 - Asserted

Software - Storage Fibre Channel

[Top](#)

HPE QLogic Fibre Channel driver component for VMware vSphere 8.0

Version: 2024.09.01 **(Recommended)**

Filename: cp062113.compsig; cp062113.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Driver version 5.4.82.1

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- o HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- o HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- o HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- o HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- o HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

HPE QLogic Fibre Channel driver component for VMware vSphere 8.0

Version: 2025.05.01 **(Recommended)**

Filename: cp066315.compsig; cp066315.zip

Important Note!

Release Notes:

[HPE QLogic Adapters Release Notes](#)

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.
This driver is only supported on VMware ESXi 8.0u3

Prerequisites

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

Enhancements

Driver version 5.4.85.0-1

This driver is only supported on VMware ESXi 8.0u3

Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

16Gb Fibre Channel Host Bus Adapter:

- o HPE SN1100Q 16GB Dual Port PCIe Fibre Channel Host Bus Adapter
- o HPE SN1100Q 16GB Single Port PCIe Fibre Channel Host Bus Adapter

32Gb Fibre Channel Host Bus Adapter:

- o HPE SN1600Q 32Gb Single Port Fibre Channel Host Bus Adapter
- o HPE SN1600Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

64Gb Fibre Channel Host Bus Adapter:

- o HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- o HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

Software - System Management

HPE Agentless Management Bundle for ESXi for HPE Gen10 and Gen10 Plus Servers

Version: 802.11.11.5 (**Recommended**)

Filename: amsdComponent_802.11.11.5.4-1_24720090.zip

[Top](#)

Fixes

See the [AMS Release Notes](#) for information about the issues resolved in this release.

Enhancements

See the [AMS Release Notes](#) for information about the enhancements in this release.

HPE Agentless Management Bundle Smart Component on ESXi for Gen10 and Gen10 Plus Servers

Version: 2025.05.01 (**Recommended**)

Filename: cp066689.compsig; cp066689.zip

Fixes

See the [AMS Release Notes](#) for information about the issues resolved in this release.

Enhancements

See the [AMS Release Notes](#) for information about the enhancements in this release.

Get connected

hpe.com/info/getconnected

Current HPE driver, support, and security alerts delivered directly to your desktop

© Copyright 2023 Hewlett Packard Enterprise Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Update August 08 2025

